Certificate of Location of Government Corner

ID#: 853104 **Description:** S 1/4 SEC COR 31 85 **Date Set:** 5/15/79 **County:** Olmsted

Section: 31 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 7' east of N-S fence and in line with fences east and west
County Survey Disk in fence post NE 23.92'
County Survey Disk in N side CP W 7.03'
County Survey Disk in CP NW 25.42'
The corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: John Ball, Deputy Surveyor, west between sections 6 & 31. 40.0 chs. Set quarter section post. RPs- 10" black oak S84 1/2°E 1048 links, 14" black oak S88°W 688 links. 50 chs.enter timber bears NW. 79.50 chs. To twp corner.

2-1870 Robert Perry, County Surveyor, (Bk. A Pg. 98 No. 140 in section 6 Kalmar) found a post standing with a stone beside it and proved it correct. He ran the line and measured from the NE corner 6 to NW corner 6 and the post was on line and only 2/3 link west of 40.0 chs. From the NE corner 6. He also found the stump of one bearing tree. He set an oak post marked 1/16S at the 1/16 west at proportionate Gov't measure (19.86 chs. Then 19.36 chs. To NW corner 6).

4-12-1971 County Surveyor found a limestone by the corner fence post. Measured from the CIM at the NW corner 6, but none of the fences agreed with Perry's measurements. Found stone and 1/16 stone east.

4-10-1979 County Surveyor measured east from the correct corner at NW corner 6 (a stone found 7.23' west and .5' south of the CIM in place in 1971) Perry's measure to the 1/16 east and dug under the E-W fence. Found a 9"x9" square mark in clean clay 11.2' west and approx. 1' south of the corner post to the fence north into section 31. Projected the line from the NW corner 6' over the mark found and again took Perry's measure. The point came 7' east of the corner post at the s 1/4 corner 31. Dug for the corner, but found nothing. The stone found by the corner post in 1971 is now gone.

5-15-1979 County Surveyor set a CIM over a 1/2"x2' iron on the line and at Perry's prorated measure from the NW corner 6 over the mark found at the 1/16 east on 4-10-1979. RPs- CSD in corner post NW 25.42', CSD in north side corner post W 7.03', CSD in fence post NE 23.92'. CIM 1' deep.

12-8-2004 County Surveyor found CIM down 1.5' in good condition.

12-14-2004 County Surveyor found CIM down 1.5' in good condition.

2-24-2006 County Surveyor found CIM down 1.5' in good condition.