Certificate of Location of Government Corner

ID#: 853106 **Description:** W 1/4 SEC COR 31 85 **Date Set:** 8/7/1989 **County:** Olmsted

Section: 31 **Township:** 108N **Range:** 15W **Monument Description:** 5/8" brass plug

Reference Ties:

The corner falls 0.2' east of centerline of CSAH 5, 1' north of centerline of twp road west and 14' south of fence east
County Survey Disk in PP #23176 SW 63.38'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: John Ball, Deputy Surveyor, North between sections 31 & 36. 40.0 chs. Set quarter section post. 6" burr oak N88°E 243 links, 5" burr oak N4°W 345 links.

8-1857 E.P. Bircher, Surveyor, and J.B. Fellows, Deputy Surveyor, Old Road Book--Road No.66) surveyed the road on the west line of section 31.

1912 Charles Larson, Dodge County Surveyor, (Book A Pg. 23, Dodge County Records) used corner (no description). Measured 20.05 chs. West to the line fence coming to road.

1940 Dodge County Highway Dept. (Dodge county highway department Bk. 22 & 131) assumed corner near fence line east.

5-8-1980 County Surveyor dug from the centeline of CR #5 west for 8' and found nothing.

5-9&16-1980 County Surveyor dug at 1/16 north and found nothing.

5-12-1980 County Surveyor dug from centerline of CR #5 east 7' and found nothing. We also dug at 1/16 south and found nothing.

5-19-1980 County Surveyor set a 1/2"x18" rod as the corner. This corner is set E-W on line from the SW corner 31 to the NW corner 31 and N-S to hold the 1/16 Nouth as near as possible to the fence East and the 1/16 south as near as possible to a point 33' north of a row of huge maple trees running west on the south side of the road west here. RPs-CSD in SE side pp# 23176 SW 47.72', punch hole in top north end 18" CMP in road west NW 35.41. 1/16 north set a 1/2"x18" iron midway and on line. Corner 2' west of centerline and 1' south fence line east. 1/16 south set a 1/2"x18" rod midway and on line. Corner 2' south centerline road west and 5' west of centerline N-S road. Corner came 33'± north of line of large maple running west on south side of road west. RPs- CSD in pp #23101 SW 43.75, CSD in pp #23171 NW 48.89, CSD in PP #53100 SE 59.01.

7-15-1985 County Surveyor, corner may be destroyed in road construction. Took additonal references. Set 5/8" rerod in north edge crushed rock road running west at centerline of field drive on north side of road. RP- CSD in pp #23177.

8-7-1989 county highway department set 5/8" brass plug in centerline CR #5. RP- county highway department in pp SW 63.38'. 1/16 south of w 1/4 county highway department set 5/8" brass plug in centerline CR #5 & CR #14. RPs-county highway department disc in pp SW 69.82', county highway department disc in cut off telephone pole NW 82.55', county highway department disc in cut off telephone pole NE 84.60'

12-9-2004 County Surveyor found 5/8" brass plug at surface in good condition.

10-23-2006 County Surveyor found 5/8" brass plug at surface a little loose in concrete crack.