Certificate of Location of Government Corner

ID#: 853205 **Description:** S SEC COR 31 32 85 **Date Set:** 5/9/79 **County:** Olmsted

Section: 32 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 37' SW of centerline of twp road on curve, 4' east of centerline of twp road north and in line of centerline of twp road east
Angle iron CP NE 50.3'
County Survey Disk in NW side PP #22920 (up 6') SW 46.80'
Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

1-1853 Gov't Notes: John Ball, Deputy Surveyor; West between sections 5 & 32. 80.00 chs set post corner to sections 5-6-31-32. RPs-10" black oak N75°W27 links, 10" black oak N11°E100 links 14" black oak S1 1/2°W61 links, & 12" black oak S1°E60 links.

4-1870 Robert Perry, County Surveyor, (Bk.A Pg.98 No.140)found a post standing and found 2 bearing trees standing and the stumps of two others which he compared and found correct. He found the N 1/4 corner 6 to be 40 chs. West of this corner and on line to the NW corner 6 he set an oak post at the 1/16 west of the N 1/4 corner 6 and at proportionate Gov't Measure.

6-1910 C. Larson , a surveyor, (Bk.B Pg.128) found a stone at this corner.

4-12-1971 County Surveyor measured from the CIM at the NW corner 6 east to the N 1/4 corner 5. Set a small rod on line fraom the NW corner 6 over a limestone found by the corner post at the N 1/4 corner 6 and midway between this stone and the N 1/4 corner 5, but couldn't agree with Perry's measurements across the north line of section 6.

11-10-1971 County Surveyor dug with the backhoe for this corner. Dug down to clean yellow soil and found the old road bed to be on yellow soil. Found nothing further except a large 2' diameter boulder in the fill part of the road shoulder (which couldn't be the original corner since it is in the fill, but could be the corner found by Larson if it is a corner stone at all) 10 to 12 feet west of the rod location. Set a 3/4" pipe at the location of the rod set 4-12-1971.

5-9-1979 County Surveyor after finding the correct corner at the NW corner 6 (a stone found 7.23' west and .50' south of previous CIM) and the mark from Perry's stake at the 1/16 east, we set a CIM as the corner on line from the NW corner 6 over the mark at the 1/16 east and at Perry's prorated measure (prorated against his measure from the NW corner 6 to the 1/16 east which we measured at just .43' shorter than his recorded measure). We set the N 1/4 corner 6 by the same method and it came approx. 7' east of the corner post. The stone found at the corner post there in 1971 when the ground was frozen and we couldn't dig is now gone. The CIM at south section corner 31-33 is 1.68' north and 10.14' west of the pipe set 11-10-1971 (removed).

6-3-2004 County Surveyor found CIM down 0.7' in good condition. Set post w/sign 2' south.