Certificate of Location of Government Corner

ID#: 853206 **Description:** 1/4 SEC COR 31 32 85 **Date Set:** 9/23/2005 **County:** Olmsted

Section: 32 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1' east of centerline of N-S twp road and in line with fence east
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Cushing, 40.00 set 1/4 section post from which a Burr Oak 8 in. S57E 90 links. Burr Oak 14 in. S32W 76 links.

4-1875 Hunter (P.269 No.267 S.32) S. Maliran, found stone planted in center road set by Robt. Perry tested by SW BT still standing. No measurements etc.

1950 Co. H.D. (B.194 P.4) 16 south set drag tooth. Disc in TP NE 33.6, disc in twin poplar SE 92.54 (found 1979), Newer ties 1959 disc in tele P NE 58.12 (found 1979), disc TP SW 54.45 (found disc in power pole 1979), disc in TP SE (gone 1979). Meas west 5211.0 to 1/16 between SW 31 and W 1/4 31. 5282.6 Meas east to assumed 1/16 corner.

10-19-1971 County Surveyor dug entire road surface 4' N&S of fence east. Sta 2639± from stone at NE 31. Corner in area where road has quite sharp slope from some 300' south crest, road worn out and gone to bare clay and corner with it. A lost corner. Could be replaced fairly close by line from stone (CIM over) at E 1/4 32 and center 32. Property corner of 3 farms, considering that 1/16 corner west of E 1/4 32 set twice, entire fences of mile line could be considered a monument in itself enough to obtain N-S of corner. Fence leading east from 1/4 31-32 has decided curve in it close to corner. Could set corner in center road as recorded or run aerial and intersect. Believe this not advisable. Meas NE 31 to SE 31 as set 5274.1 midway 2637.05 fence E 2639 from N.

5-7-1979 County Surveyor, 1/16 south (Remon Book 1979 Pages 49 and 50). Set a concrete nail as a traverse point 2' north of centerline Co. Rd 14 and in centerline roads north and south and at 58.12 from an old County Highway Department disc in a cut off pole NE and at 82.54 from and old County Highway Department disc in twin poplar SE. We also found an old County Highway Department disc in a power pole SW using the County Highway Department ties to this pole and the cottonwood tree would pull the point west appx .7. We dug from a point 1' south of the traverse, south for 4', west for 4', and east for 4' as follows. There was an old road 4' deep with 6" to 1' of black dirt beneath. There was still frost in this dirt but we were able to dig through to clay. The only thing we found was one small piece of limestone (about 5" in diameter). Shattered just beneath the old road 3' south and 1/2' west of the traverse nail and a larger piece of limestone standing on top of the old road in fill 4' south and 3' to 4' east of the traverse nail.

12-8-97 At 1/4 cor 31-32: Vince Fangman using location in centerline road and line of fence east. See cert 8532-3933 and cert 8530-3209. Ok'd this point for land consultants use also. Will set monument according to Vince's measurements.

5-6-2004 Vince Fangman set 1/2" pipe w/cap down 0.4'

6-3-2004 County Surveyor found 1/2" pipe w/cap down 0.4' in good condition.

9-23-2005 County Surveyor found 1/2" pipe with cap down 0.4' in good condition. Took local ties and removed pipe. Set CIC on a 5.0' telspar pipe down 0.4' at pipe location.

7-1-2011 County survey crew found telspar pipe bent near the top. Cut off the bent section of pipe and reset cast iron cap. The cast iron cap is down 1.2'.