Certificate of Location of Government Corner

ID#: 853304 **Description:** S 1/4 SEC COR 33 85 **Date Set:** 11/13/75 **County:** Olmsted

Section: 33 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 3' east of fence north and 9' north of fence west
Spike in E side 30" Elm N 240.52'
County Survey Disk in E side CP SSW 9.19'
Post w/sign 3' W
This corner is located by GPS measurement

Corner History:

8-1853 Gov't Notes: John Ball, Deputy Surveyor; West between sections 4 & 33. 40.0 chs. Set quarter section post. RPs- 15" black walnut S30°W 15 links, 5" elm N72°E 13 links.

11-1856 T. Hunter shows 1/4 post.

2-1863 P.C. Compson Pg. 68 No. 95 shows 1/4 stake used for breakdown of SW 1/4 S 33

2-1867 H. E. Horton Pg. 81 No. 122 shows 1/4 corner.

8-1893 W. Fraser Pg. 18 No. 30 found stake as 1/4 corner from bearing tree planted stone 2x4x17.

12-1897 William Fraser (Pg.614 No.558), County Surveyor found 2"x4"x17" stone placed in place of old stake found in an 8-1893 survey. (Could find no record of this survey)

4-1905 Robert Fraser (Pg.78B), County Surveyor found stone with stake beside it at corner of fence post.

12-1916 Dave Williams (by John Kerr Pg.264B), Count Surveyor found stone and stake.

1931 John Kerr (Bk.6 Pg.2) County Surveyor found stone and stake by corner fence post. Used corner to set south section corner 33-34 midway and on line.

1935 county highway department (Bk.78)-iron pipe and stone at fence corner.

11-13-1975 County Surveyor found that new fences have been built in the area of the corner and trees cleared. Dug from new corner post north 20' on east and west sides of fence and large area north and east of corner post at our computed location. Found nothing. Set corner at double the line and measure from s 1/4 corner section 34 over John Kerr's 1931 location of south section corner 33-34 (true corner and Kerr's corner at south section corner 33-34 were both found and referenced in 1970). Set CIM (deep) over 1/2"x18" rod as corner.

7-11-2005 County Surveyor found CIM down 1' in good condition.