Certificate of Location of Government Corner

ID#: 853305 **Description:** S SEC COR 32 33 85 **Date Set:** 6/19/70 **County:** Olmsted

Section: 33 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1/2' south of fence east, 1' south of fence west and 4' west of centerline of CR 105
20d spike in N side large Willow (5' up) E 85.22'
Bottle cap in top of CP E 37.0'
Bottle cap in PP #22726 W 26.8'
This corner is located by GPS measurement

Corner History:

Gov't Notes: 80.00 set post corner to sections 4-5-32-33. White Oak 20" N 105 32, Black Oak 10" N 45 W 68, White Oak 14" S 80 W 25, Black Oak 24' S 51 E 45.

4-1875 T. Hunter book 269 No. 267 found hole made by original stake checked by all bearing trees. Drove new stake.

4-1905 R. Fraser P. 78 B found old stake and drove iron gas pipe.

6-1910 C. Larson P. 128 B found gas pipe and iron bolt.

11-1916 J. Kerr P. 260 B found iron stake and bolt.

1935 county highway department found iron pipe and bolt.

6-19-1970 County Surveyor found 1 1/4"x33" old pipe and 7/8"x24" bridge bolt. Set CIM over bridge bolt down 6" with glass etc...

7-23-1999 County Surveyor found CIM in good condition down 0.9'.

8-19-2003 County Surveyor found CIM down 0.8' in good condition.

6-24-2005 County Surveyor found CIM in good condition down 0.8'. Did not check ties but all ties are there except 20d spike in willow tree has been grown over.