Certificate of Location of Government Corner

ID#: 853306 **Description:** 1/4 SEC COR 32 33 85 **Date Set:** 7/19/2004 **County:** Olmsted

Section: 33 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' east of centerline of CR 105, in line with old fence row east and 19 1/2' south of centerline of field entrance west
Punched cross in N end 15" CMP NW 39.74'
Punched cross in S end 15" CMP WNW 27.6'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: 40.0 set 1/4 section post and made trench. RP-8" burr oak S89 E 61 links.

1863 PC. Compton Pg.68 No.95; 1/4 section post gone. Established it by US Field Notes from witness trees, used corner for breakdown of SW 1/4 section 33.

4-1875 T. Hunter Pg.269 No.267; Found original stake standing, all witness trees gone, nut one stump, corner correct. 16 west set stake M & L 19.96. RPs- 10" jack oak S77 1/2° E 51 1/2 links, 16 center NE 1/4 set stake M & L 19.99 on N-S 1/16 line.

12-1897 W. Fraser Pg.614 No.558; Found stone set by D.Pierce, Pike, and others. Tested stump of 1 witness tree set on Hunter corner. 16 east set markes stake M & L 19.85.

4-1905 R. Fraser Pg. 78B found stone. East found 1/16 stake. Set 1/64 stake M & L, 1/16 south drove iron stake M & L, and 1/64 corner east of above 1/16 drove iron M & L N & S.

6-27-1910 Charles Larson Pg. 128 B. Found stone set in former survey.

12-4-1970 County Surveyor found Highum (Dodge Co.) pipe.

10-13-1971 County Surveyor dug and found 6x7x15 limestone down 2.5'. Set CIM over original stone. Corner came 1.7' east and 0.2' south of highway pipe.

7-19-2004 County Surveyor found CIM down 0.4' leaning badly. Removed CIM and found 6x8x18 stone down 2.3' in good condition. Removed stone and set 5' telspar pipe w/cast iron cap down 0.4' at stone position.