Certificate of Location of Government Corner

ID#: 853406 **Description:** 1/4 SEC COR 33 34 85 **Date Set:** 11/9/71 **County:** Olmsted

Section: 34 **Township:** 108N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in open field down 1'
Backward sign on post 300' west on edge of woods
Backward sign on post 165' south on edge of woods
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes: Cushing; 40.0 set 1/4 section post. RPs- white oak S72 W55 links, 18" white oak N72 E45 links.

1856 Thomas Hunter Pg.18 N0.30: 1/16 west 19.72 chs. M & L-B.T.'s(S47 1/2°W16 lks)(S44 3/4°E 17 1/2 lks) 1/16 south 19.80 chs M & L-B.T.'s(N82°W 12lks)(S50°W59 links).

12-1897 W Fraser Pg.614 No.558; Found stake remains of old gov't stake. Tested NEBT and gov't notes and found to be correct. Set stone in its place. 16 south set stone, 16 north set drag tooth, west set property stakes.

12-1916 D. Williams, J. Kerr; Found stone in place as 1/4 corner. South 1/16 stone found (1314.5). Set stone 6x6x30. Some time a 1" pipe was set south 330'. Corner stone removed and destroyed byLeonard Moon in 1950s.

10-1965 J. Kerr B90 Pg.72; Relocated corner on direct line between 1/16 shaft, avered to be where drag tooth was found and 1" pipe just east of corner post of fence west and 1306.5 south of shaft & 300'. Set CIM over 5/8"x12" rebar. (This corner wrong as there is proven kink in this line).

11-9-1971 County Surveyor reset CIM in correct location 0.4' south and 5.3' west of CIM set 10-1965.

8-22-2005 County Surveyor found CIM in good condition down 0.8' in cultivated field. Did not locate any trees but fence to the west in good shape, fence to the south down and partially destroyed.