Certificate of Location of Government Corner

ID#: 853604 **Description:** S 1/4 SEC COR 36 85 **Date Set:** 6/7/1999 **County:** Olmsted

Section: 36 **Township:** 108N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1 1/2' south of centerline of CSAH 14 and 5 1/2' east of centerline of CSAH 3 north
County Survey Disk in PP #23844 SW 39.90'
NW corner of Golden Guitar bar ESE 131.77'
SE corner of main church foundation up 2' NW 83.97'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: John Ball, Deputy Surveyor; West between sections 1 & 36, 40.00 chs. Set post and deposited handfull of small stones for quarter section post. Built mound with trench and planted Osage Orange SE and apple seed NE.

6-1878 Thomas Hunter records a stone at the 1/4 corner when he laid out the town of Douglas.

4-1919 Charles Armstrong (Pg.302B) set a 4"xx17"x18" stone at the 1/16 west midway and on line at 1316. Found a stone and iron bolt at the SW corner 36.

5-1948 John Kerr (Bk.36 Pg.73), County Surveyor, shows "no point in place" at the 1/4 corner, but set a 1"X3' long pipe and referenced it it the foundation of the church NW and the old store SW. He found the 1/16 west and records an iron at the SW corner 36.

10-1965 John Kerr (Bk.90 Pg.62) found 1/4 corner of section in place and set CIM over.

10-26-1972 County Surveyor measured 1314.8' from a 1/2" rod at the 1/16 west to a spike in place at the S 1/4 corner 36.

6-2 & 7-1977 County Surveyor found Kerr's 1/2" rod at the 1/16 west to be over Armstrong's recorded stone. Set a 1/2" rod over the stone.

6-7-1977 County Surveyor found Kerr's CIM at the S 1/4 corner 36 to be nearly on the line from a pipe at S section corner 35-36 over the 1/2" rod set over the stone at the 1/16 East. Dug down and found the CIM over a 1"x15" pipe packed in limestone which fit Kerr's ties to the church and store. Removed CIM and set a 1/2"x2" rod over the pipe. The road is to be graded.

11-8-1977 County Surveyor set a CIM in place of the 1/2" rod set 6-7-1977.

5-13-1998 County Surveyor found CIM in good condition 1' south of centerline CR 14. referenced corner before cold recycling bituminous surface of CR 14.

9-21-1998 County Surveyor set P.K. Nail in new bituminous surface from 5-13-1998 reference.

6-7-1999 County Surveyor set 1" square pipe w/cap at surface using previously referenced location.

3-26-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.

2-15-2008 County Surveyor found 1" square pipe w/cap at surface in good condition.

12-3-2013 County survey crew found 1" square pipe in good condition