Certificate of Location of Government Corner

ID#: 853605 **Description:** S SEC COR 35 36 85 **Date Set:** 6/7/99 **County:** Olmsted

Section: 36 **Township:** 108N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1' north of centerline of CSAH 14 and 68' west of cemetery driveway north
Ref pipe SE 94.88'
Spike in Spruce N 37.55'
County Survey Disk in PP #23807 S 39.86'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: 80.00 section corner post to sections 1-2-35-36. RPs-14" burr oak N30° W 90, 10" burr oak N9° E 67, 10" burr oak S 39 1/2° E 54, 14" black oak S 83° W 50.

2-1882 T. Hunter Pg.373 No.364; Found stone in center road placed by Daniel Daly and other settlers where original corner stood, tested by stumps of 2 witness trees, west 39.77 to fence south at S 1/4 35.

4-1919 Charles Armstrong, Pg.302 B; Found stone and iron bolt as corner. 16 east set stone 4x17x18 1316' M & L. Now iron rod numerous ties, see S 1/4 36. Cemetary laid out from original corner has been tested.

1948 Bk.155 Pg.6; Iron pipe in black top as conrer. RPs-disc in fence post NE 46.0(45.65, disc in spruce N 37.0 (37.2 measured west 2622.5.

1948 Center Grove Cemetary, New Layout, Bk.39 Pg.61; 1" iron pipe 33' north S 35-36 then north 196.5 to NE corner plot 1" pipe, then west 172.5' 90°10' interior anlge to 1" pipe then south 196.5 to 1" pipe 33' north of range line. Lots 18x18 4' walks. Found section corner in road easily.

1966 county highway department Bk.318; Found 3/4" pipe with 60d riser. RPs- spike in pine north 37.55 spike in pine NW 41.13, spike in pp S 39.94. Measured east 1315.18(R1316.0), measured west 2622.10

5-1982 Vince Fangman called to report on this corner. He found 5/8" pipe inplace which he said he set over spike found when he worked for McGhie & Betts. He pulled pipe out and checked for CIM under it. Found pipe to be about 18" long and over something hard either CIM that deep or pipe is on top of stone as above records indicate no CIM in place. He checked ties from 1966 county highway department which are shown corrected in blue.

5-15-1998 County Surveyor found pipe in good condition in centerline C.R. #14. Referenced corner before cold recycling bituminous surface of C.R. #14.

9-25-1998 County Surveyor set P.K. Nail in bituminous surface from 5-15-1998 reference.

6-7-1999 County Surveyor set 1" square pipe w/cap at surface.

3-26-2004 County Surveyor found 1" square pipe w/cap at surface in good condition.