Certificate of Location of Government Corner

ID#: 953104 **Description:** S 1/4 SEC COR 31 95 **Date Set:** 11/16/2001 **County:** Goodhue

Section: 31 **Township:** 109N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1 1/2' south of centerline of E-W road and 10' east of fence north
County Survey Disk in NE side PP SE 52.05'
County Survey Disk in E side CP NW 30.33'
County highway disk in PP SW 63.15'
County highway disk in SW side 11" Box Elder NW 36.30'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes Elisha S. Norris, Deputy Surveyor; West corrected on the south side of section 31. 40.0 chs. set quarter section post. RPs- 7" cherry N37°W 73 links, 7" aspen N75°E 69 links.

9-1882 Thomas Hunter (Pg.379 No.370) County Surveyor measured east from the fence line north at this corner to locate the north section corner 5-6 T108N R15W.

9-16-1976 Olmsted County Surveyor found 1 1/8"x2"x10" iron 4' deep at near gov't measure. Set CIM over 1/2"x2' rod over the iron.

7-1981 Doug Rude, Crew Chief for Yaggy Associates, Inc., found a cast iron monument for the corner. New land ties were recorded. The monument is accepted as marking the Original Public Land Survey corner.

11-16-2001 Goodhue County Surveyor found 5/8" pipe over CIM. Set telspar monument.

3-23-2005 Olmsted County Surveyor found cast iron cap on telspar pipe at surface in good condition.

1-27-2006 Olmsted County Surveyor found cast iron cap on telspar pipe down 0.1' in good condition.