Certificate of Location of Government Corner

ID#: 953404 **Description:** S 1/4 SEC COR 34 95 **Date Set:** 11/16/2001 **County:** Olmsted

Section: 34 **Township:** 109N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

Spike in W side Gov't Brg. Tree N41°39' 56"W 147.86'
County Survey Disk in NE side TCM guard post NE 31.86'
Drill hole in concrete culvert WNW 103.07'
This corner is located by GPS reference stations "Witt A & 850207"

Corner History:

9-1853 Gov't Notes Elisha S. Norris, Deputy Surveyor; West corrected on south side of section 34. 40.0 chs. set quarter section post. RPs- 12" burr oak N43°E 224 links, 6" burr oak N48°E 76 links.

5-14-1975 Olmsted County Surveyor dug at this location and found the ground very disturbed. Found small limestone deep in the subsoil, but there was no evidence of black dirt etc. as if it had been set. Reset a 1/2"x30" rod.

CORRECTION OF CORNER: the corner is 1.85' south and .12' east of the 1/2" rod set in 1975. (Removed)

11-9-1981 Olmsted County Surveyor found 4"x5"x12" broken top stone 3.77 east and .25 south of 1/2" iron location. Read bearing and distance from stone to possible bearing tree N40°W 149'. Set 1/2" rod back.

11-25-1981 Olmsted County Surveyor set CIC on square pipe. Corner is on the northerly slope of approach to TH 52 to twp road running west and is 28 1/2' north of the center of the black top mat on curve in the approach. Set at the intersection Gov't tie to Gov't bearing tree and closing corner at 2-3 found in 1975.

6-25-2001 Olmsted County Surveyor visited area of corner and found nothing.

11-16-2001 Goodhue County Surveyor set cast iron cap on telspar pipe.

3-17-2006 Olmsted County Surveyor found CIC on telspar pipe down 0.1' in good condition. CSD with nail in NE side TCM guard post NE 31.86'.