Certificate of Location of Government Corner

ID#: 953405 **Description:** S SEC COR 33 34 95 **Date Set:** 11/17/1981 **County:** Goodhue

Section: 34 **Township:** 109N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 56' north of north edge of river
County Survey Disk in 16" Basswood NE 54.24'
County Survey Disk in 9" Elm SW 36.92'
County Survey Disk in 16" Basswood NNW 28.70'
Post w/sign 2' north
This corner is located by GPS reference stations "Hassler B & C"

Corner History:

9-1853 Gov't Notes Elisha S. Norris, Deputy Surveyor; West on corrected south line of section 34. 80.0 chs. Set post for section corner. RPs- 12" Elm N57°W 38 links, Linden N65°E 12 links.

1967 P. Highum (Survey done for farmer in section 33) set 1" iron as corner. No known method for setting at this location.

11-2-1981 Olmsted County Surveyor dug for Highum's iron and found nothing.

11-3-1981 Olmsted County Surveyor found 2" diameter stake 18" long down 16" standing 13.06' west and .19' south of Highum's iron (replaced). Removed stake to office and drove a 3/4" square pipe at its location. Chained 158' west to the upper bank.

11-17-1981 Olmsted County Surveyor set telspar pipe w/cast iron cap over 3/4" square pipe set 11-3-1981.

8-30-2001 Olmsted County Surveyor found cast iron cap on telspar pipe up 0.3' in good condition.