Nov 18 1974 ~~set CIM over 3/4x3' iron rod~~ M+L ~~2652.33 etc.~~ ①
5-26-78 set CIM 7.05 W ut
5 1/4 corner Sec 2 10 4-14 #440204

~~No known Bearings on this cor~~

August 1974 - Dug at this corner - found nothing but large boulders. Referenced out a point set M+L.

November 18, 1974 Set a C.I.M. midway - on line at 2652.33.
Set a C.I.M. over a 3/4" x 3' iron rod.
the corner falls 3' E. of the fence South - 6'
South of ℄ of travelled road.
R.P.s
N.W. cor. Wetland conc. culv. headwall S.E. 11.39
N.W. cor. Wetland conc. Culv. headwall N.E. 25.75

1/4 Cor. Wrong Must reset R.B. 10-1977

(moves West 75' & positive North)

In August 1974 we also dug extensively at the 1/16 cor. East because one of the local farmers claimed there was a stone here — found Nothing

"over"

South ¼ Corner Section 2 High Forest 104-14 ⑤
#440204

5-23-78 Cont.
RP's: NW corner of West end of South headwall of Concrete culvert SE 15.28
NW corner of West end of North headwall of concrete culvert NE 28.02

5-26-78 Drove the ⅝" rod down and set a CIM on it. Removed the old CIM.

Gov't Notes Ball 1853
West on true line between sections 2-11.
40.00 Set ¼ section post. Deposited charcoal and raised mound of earth &sod & cut trench & planted osage orange seeds N&S between pits and trench.

5-3-1979 Retied CIM - old Ties ambiguous!
RP's: Punch hole top center (.28 from South edge) South concrete headwall SE 21.24
Punch hole top center (.25 from North edge) North concrete headwall NE 30.35

on Oct. 13, 1977 R.B. found record of T.H. 1882 Survey in S.E.1/4 Sec. 2-104-14 in road Survey notes in a T.H. field book furnished by C.A. Armstrong on Oct. 7, 1977.

T.H. notes meas. across S. line Sec. 2 as 40.09 W. 1/2 - 20.16 & 20.16 E. 1/2 and on 1/4 line from Cor. Sec. 2 East 20.12 & 20.12 To E.1/4 Cor.

5-18-78 1/16th East: Dug at 1330.56 From S.E. 2 as per T.H. Field Bk. and from present Sec line N. for 7' by 4' deep. Found that we had already covered the area in 1974.

5-22-78 Dug from a pt. 4' West of the CIM set in 1974 for 8' West 5' South and 7' North by 6' deep to clay. found nothing.

5-23-78 Set a 5/8" x 18" rod 7.05 West of the CIM, on the line between the section corner and at proraled T. Hunter measure. The Corner is South of the corner post on the North side of the road, 5' West of the fence line So. and 7' South of ℄ E-W road.

The corner is 8' South of ℄ E-W road, in line with main line of fence (± 400' South) South, 4' West of local fence South, and in line with fence North (only pipe corner post, brace post, and one steel post remain).