/ Set 1 1/4" pipe a perm. cor. on aug 5, 1974

#440206 ①

1/4 corner 2-3 Hi Forest 104-14.

4-1875 Hunter P271 No 269. L3 L G 9 ish.
Corner gone but stumps of both B trees plainly marked
re-set corner with 8 x 10 x 15 boulder stone.
- meas south 40.23
- meas west 39.96

1-1902 W Fraser P29 B L3 Woolridge estate
found stone set as 1/4 corner P271. likely.
~~At~~ west set iron rod. at 1320' on line to W 1/4 3 over)
- drove iron stake 9.90' north of above 1/4 corner also
" " " " " of above 1/4 cor on section line

1945 Jerry Blake - Frank Eaton surveyors 562-3-4 B.
E ¼ cor gone by road work could not find any of the iron pins placed by 9 rods; much construction & debris found stone with cross 990' north of corner 8x8x24 with cross.

5-11-1878 Hunter (unrecorded no 337½) A Knapp. L Rich.
found boulder. 8 X 10 X 15.
16 west 19.98 M & L to center then 20.03½ M & L.
west to west ¼ cor. Check this Survey

Aug. 5, 1974 Co. Surveyor
Set 1¼" pipe in Bit. Surface Hwy 63 - 8' E. of ℄
Set This Corner by projecting Line from N. over 8" sq. stone at 990.0' N.
R.P.'s - C.S. Disc. in R.P. — E. NE - 66.34
C.S. Disc. in Transf. P.P. — S. SE. - 190.95

HI FOREST ¼ CORNER 2-3 #2

#=440206

Gov't Notes Ball 1853 North on true line between 2 & 3

40.00 Set ¼ section post.

Black oak 12in. S-3 W-177 lks.

Bur oak 8in. S-40 W-135 lks.