X ~~to S.T. found iron~~ aug 2 1979 found stone #440307 Set C I M. over a rod. N C R 6 (1)

section corner north 3-4 Ti Forest 10 4-14

5-1878 Hunter P343 no 337 S4 H D Morse and others all corner missing between S 432 ~~to S 32-33~~, NE3, S4 33 unclear after placed stone (N line 4) NW cor 4 meas to NE cor 3 162.60 R 161.31

making 81.15 meas at which set stone 4x8x24 at 5365.9 - 81.45 N line 3 5375.7

north 3-4. which stands on edge of embankment on north side of traveled track on line betw S 32-33 and S 33-34.

- meas south 40.22 1/2 2687.85

- meas west 40.72 1/2 to stone 6x12x25 set M & L.

4-1875 Hunter P 271 no 269 S 3 corner refered ahead to P 343- meas E 40.58 M&L

4-1906 Ch Armstrong P104B S4 A L Bruch. found recorded stone. at least stone marked on plat a typical armstrong mystery corner.

Co Hwy dept B166-P1 1945 1-1969 ties OK. | N3-4 104 -14
found cedar stake and stone mon.
Not S1/4 33
Hub N 70.88 Hub L 68.67.
~~NE corner conc fence post L 38.25~~
18" deep - 6.1' N and 1.0' west of PI Sta 55+13.0 Δ 0°13 R. - B61
Meas rec 2688.0 R 2687.85 - Spike pole SE 57.95

McGhee 1953
stake & stone with 3/4" steel rod risers.
Sp in power pole #11047 NE 122.7
" " tele " SE 57.15 Co. 57.95
top conc corner fence post L 34.15

1940 CHD B 112 P5 No deed corner.
Hub north 70.88 on transit line to hub south 68.67 with
NE cor Q Conc F.P. on same line L 32.85 Sta 81+47.7
Δ 0°13½' Lt Meas rec 2673.9.
P75 B112 found 2 survey stake risers - set 3/4 rod risers

#440307 (2)

Card #2 North 3 - 4 High Forest 10 4-14

6-8-1971 co surv. found (No Good) - Corner fd. N. ± 5' 3/4" x 3' rod badly bent on top down 6"± in lower black top road - removed and used 4' probe in hole. hit stone below very near 4' deep.
- found 8" square conc post recorded broken flush with bottom ditch area leaning slightly southwesterly.
- replaced rod flush with road surface.
- east corner conc post → ◇ | east line S. 34.2
- old disc in 9" cedar corner post, leaning SE badly S. 35.6
- Ho D nail bent up. - plumbed 18" to mac, NE 122.7
- ·:· in east end 24" culv in road to dump SSW 28.3.
- punch in rivet in end of west end 24" culv " SW 50.24 (over).
- mac west to similar rod presumed over stone 2687.8 R2687.85

6-24-71 something radically wrong with N 3-4 or N¼ 4 or both.
Conc fence post south in drainage.

N 3-4
104-14

Co H D. 1940 B112 P5. NE cor conc fe P. L. 32.85
Co H D B166 P1. cedar stake & stone mon
NE cor conc fe R L. 38.25
McGhee 1953 Stake & stone – top conc cor fe P. L 34.15
6-8-71. Co Surv. Conc post broken off or placed
flush with bottom ditch bank most easterly point S. 34.2
J Kerr B. Claims top conc post L 39.0
line projected west & double meas course. 7.6' north of Naval hub
which is 3.7' North or 11.3' from proj line from east point to meas
from south from a point proj from stone at ¼6 on E side NW¼ 4 over
cor post which is 1330 from ¼6 south. or E-W fence. This brings
N-4-5 near N edge road near where 1915 J Kerr claimed them.
6-25-71 found bottom of Conc post & rest on E side about 41' NE to rod. (Note) see N-4-4

#440307 (3)

North Sec Cor 3-4-104-14

Aug. 2 1974

Dug with backhoe & found the recorded stone.
Set a C.I.M. Punch with bit mat in C.R. #6.

R P's

Punch cross on top E end 30" C.M.P. S.S W. 39.1'

Punch hole on rivet at N end 30" C.M.P. S W. 53.20

C.S.D. on N.W side of P.P. # 11097 N.E. 122.25

Corner lies 5' North of ℄ C.R. #6 & in line with the fc. running South.

8-1931 C.H.D. Page 5 Book # 61 fd. 15" Cedar stake over stone 18" under surface. Stone falls 6.1' North & 1' West of P.I.

HI FOREST SECTION CORNER NORTH 3-4 #440307 (4)

Gov't Notes Ball 1853

79.50 Intersected Standard Parallel line 330 lks. west of ¼ section post south of section 33. Deposited charcoal and raised mound of earth & sod & cut trench and planted osage orange seeds east and west between trench and pits.