/ 8-8-1974 set C.I.M. over rod flush with bituminous surface
#440308

¼ corner North ¼ 3 Hi Forest 104=14.
4-1875 Hunter P271 no 269 ∠3 L.L. Fish.
no corner ever set by Gov't surveyors. set
stake midway north section corners of ∠3 and line
of South Sec cor 33-34
and NW cor Sec 3.
- meas ∠ 33-34 east to NE cor 3 34.48. then
~~5.63~~ to ∠ ¼ 34 total SW 34 to S¼ 34. 2275.68 2636.04
- meas east 5463 6036 & west 40.58. to section corners
2678.28

mer.

Co Hwy Dept 1940. B166 P2. N 1/4 3 104-14

3/4" iron with hub & tack.

Reccd in Tele. pole		L E	77.58
" top corner fence post		L	39.18
20 D in power pole		N W	51.90

5-11-1878 Hunter unrecorded no 337 1/2. A Knapp & L Rich.
No corner ever set. Reset by L E cor 33.
Meas west 40.58. 2678.28
Meas east 20.29 then 20.17 ? to N E cor 3

11-1940 C H D. B112 P6. Set one old spike. Sta 108+22.6
same R P S as B166 which could have been B112. P.O.T.

8-8-74 Co. Surv.
Set a c.i.m. over a rod at 404.14 from the S. sec. cor. 33-34 which is midway on line of N. line sec. 3. Did not dig at corner as talk in very deep fill. Took No references.