/ 8-9-1974 Set a C I M by elec. means. M&L 2644.16
#440404

1/4 corner south 1/4 4 Ti Forest 104-14.
5-1878 Hunter P343 no 337 S4 H D Morse & others
Corner missing, no evidence or knowledge.
at stake "bell down M & L on south line Sec. 4.
40.10 N 86 3/4 W - Bearing 1/4 line N. N 3/4° W
-16 N. set stake M & L 19.93 1/2.
-16 E set stake M & L 19.86 1/4.

8-7-1974 Dug with the backhoe and found the remains of an old stake. the stake that we found at S. Sec 4-5 was very definite + since the S. Sec cor of 3-4 was tipped + leaning East. the S 1/4 cor. moved 1.1' west + 0.6' North of the spot

we found. For this reason we reset the
cor. exactly mkd by eke. mens.

R.P.'s

C S.O. S.W. side P.P.a 10651 N.W. 48.16
C S.O E. side of an old cor. post. N. 43.16
corner falls ℄ road + 2' E fr. North

Gov't Notes Ball 1853
West on true line between sections 4-9.
40.00 set ¼ section post and deposted charcoal. Raised mound of earth and sod and cut trench and planted osage orange seesd north & south between trench & pits.