1 8-8-1974 - Set C.I.M. over iron rod over stake hole.
#440405
section corner south 4-5 Hi Forest 104-14.
5-18 78 Hunter P 343 No 337 & 4 HD Morse & others.
Corner missing, no evidence of corner after careful digging over large "span" all B trees grubbed & gone.
found line & old fence running east covered by all settlers as set from orig corner before road opened running east and road fence N & S just 2 rods from this. also E & road south. in center road fence on east & west sides just 2 rods
- set stake "well down" at this point
- meas east 40.10 to stake "well down" N & L N 86 3/4 W
- meas north 40.00 to large boulder. N 1° W

8-8-1974 as Surv.
Dug with tractor - found a very definite - deep stake hole in the subsoil. Put an iron

rod over the hole + set a C.M. over an iron rod.

P.P's

C.S.D. on S.E. side P.P.# 10634 N.E. 35.45

Center tel. box. S.W. 53.9'

Spike + C.S.H. on W side 24" OAK. S.E. 111.4

Corner was 5' deep + Pile in the

N.E. corner of the intersection

Gov't Notes Ball 1853
North between sections 8 & 9.
80.00 set post to section corner.
Bur OAK 6in. ?42¼ E-358 lks.
Bur Oak 7in. S-44 &3/4 W-585 lks.
Bur Oak 5in. N-36 & 3/4 E-453 lks.