#440604

X 11-5-71 found co rod in fence tile cor S 5 E 6

10-24-72 set 5/8" rod as corner - removed rod in tile. (1)

1/4 Corner south 1/4 6 Hi Forest 104-14

6-1878 Hunter P 348 No 341 S6 C L Goodrich & others.

Corner missing but NE BT standing and SE BT stump in place. reset stake. Came in center road just 2 rods from east road fence owned by Mr Dicky as having been set thus when orig stake was standing.

10-1940 Co Hwy Dept. B109 P77. found 1/2" rod in center of tile and concrete monument set with 3/4" iron bar riser.

80 L. in SE side 18" oak orig Bkg WSW 34.5

Slice Cor F post W 43.5

2x2 Hub in fence line (hub & cor F.P. 86.5 apart.) SSW 98.25

1927. B48 P17 Co HD.
found stake above stone - claimed riser did not dig stone.
80 D in 18" oak W S W. 1940: 34.5 35.0. org B tree SE end tree
80 D in tile Pole NW 49.8,
1940 Meas north to center 6. 2659.2'

Ch Armstrong records in small book.
Bonche 10 x 10 x 16 S 84 W 16" oak. 47 lks 31.02
11-5-91 Co surv. dug entire area by hand in range of RPS to subsoil - very stony, mixed, wood deep, much pre-dug. - found rod riser over clay tile filled with concrete, ½" rod in center.
34.3 3'± S of W to head of 30 D in base of old oak NE corner.
98.6 S S W to oak but with MHD chisel log replace org but
30.55 ESE to cross cut in N end center 18" cone field elev.
47.22 SE " S "
Meas from Center 6 S to fence E 1657.0, To replace tile corner 2659.82

Card # 2 South 1/4 6 High Forest 104-14 (2)
#440604
11-29-71 Meas east to farm tile with rod in center
2660.7 Rich Armstrong unrecorded survey 40.38 2665.1
12-8-71 found true S 5-6. 6.3 south and 4.9 west of tile mon
Making meas E-W south line of SE 1/4 6 2655.8
or 9.3' short.
10-24-72 dedug area with Keller backhoe. found road
down to green super sticky clay. corner gone.
- on prior running of complex electronic traverse ending
at N 1/4 6 and using center 6 as set would burn corner
4.02' west of iron in place. which comes near exact
of 47 like = 3.02' from center of Ch. Armstrong bearing tree
then 8" now close to 3' and very old and may be dead. (over

reset corner with 3/4" x 4' iron on transit bearing of S 84° W and 4.02 W of rod which came 31'± from tree.
— Meas north to 5/8" x 5.2' rod set at SW corner 50 acre tract of which SE corner was found a Mended boulder stone.
- rod set on line to S 1/4 6 as re-set and center 6.
S 1/4 to iron 997.68 - iron to center 6 1662.79
iron east to stone SE cor 50 acres 1313.85
- rod bears 78.48 NW to nail in knot on NE side PP 10569
no plate up 8' nail up 4'.
RP S 1/4 6 33.7 ESE to small cross in N end 18" Conc culv.
Co rod in hole removed. 30.55.
48.86 SE to small cross in S end 18" Conc culv 47.22
30.3 4'S of W to nail in NE side org Ch Armstrong Elm. 34.3.

HI FOREST SOUTH ¼ CORNER 6 #440604 #3
Gov't Notes Ball 1853
East on true line between sections 6 & 7.
40.30 Set ¼ section post.
Bur Oak 10in. S-9½ E-105 lks.
Bur Oak 8in. N-22 E-128 lks.