X 6-7-79 CIM

#450106 Card # 1

1/4 Corner 1 - 2 High Forest 104-15.

6-1877 Hunter P 320 no 314. L2. Samuel Saulsberry, J Pribb Corner gone - NEBT gone. SEBT-a stump ardied by mr. L. Shipper as used by surveyors as BT and has memory of marks on tree. this would make mear north of 1/4 corner 3 rods long. - reset stake from field notes using this stump..

6-1878 Hunter P350 no 342 L1. J S Pierson

corner gone all trees & stumps now gone - controversy among settlers as to location. Compromise reached and stake set very near orig location.

-16 east set stake N & L ~~20.05~~ 20.0 1/2

-16 north set temp stake 20.84 chen 18.87 To sec cor.

-16 center NW 1/4 Sec 1 set stake on N-S 1/16 line 20.73 North of 1/16 cor.

6-1895 W Fraser ~~Hunter~~ P637 No 574 & 2 Carl Bittcher, A Wilmott.
stake set P350 gone completely. found center sec 1 and
1/16 cor between center & W 1/4 stakes set by Hunter P350.
run this line & meas carefully. and drove gas pipe
4 feet long well down - also meas line north & came
within 1 link a short of Hunter.
— 16 west set stone 5x5x20 M & L. 20.31.

5-1940 Co Hwy Dept. B109P76. Meas west 2679.7
found pipe set 3/4" rod riser on west side pink hardhead.
1 1/2" pipe ~~dug out~~ found 1979 N-33.05 this corner in center road ~~and~~ east shoulder
Spike telepole. ~~S5W. 80.6~~ S01W 80.6 of road running south.
" Twin Plum tree N.W. ~~52.54~~ None corner in PI 10°28½' Lt going east

---

16 east - 1320.3 to 1/16. then 1319.5 to Center 1. R.P. set hub
This corner is limestone - 4" sq. at top. near N-S fence line. 99.7 north
it is .2 N of direct line and .3 W of midway. 2639.9. R 2640.66 on fence line
see Center 1.

#450106 Card # 2

1/4 Corner 1-2 High Forest 104-15

C.H.D. 1925 Book # 38 Page 83 shows Iron Pipe over stone Monument

Govt Notes J.W. Ball 1853

Set A section post
Black Oak 12" W 52 E 400 1/K's
Black Oak 10" S 10½ E 785 1/K's

1/4 Cor.

1979 Revon. BK. Pages 54, 55, 60, 68, 83

Page 54 & 55 Set concrete nail traverse point on line from C.S. iron at the E. 1/4 Cor. over the nail found at the Center.

Page 60: May 17, 1979 Found a 3/4" x 2' rod in the blacktop and the C.H.D. R.P. pipe recorded 33.15 N of the corner. The rod measured only 32.2 so we removed it and dipped a 3/4" x 38" rod (bent over) appx 1' South beneath the blacktop. We removed the rod after referencing to Concrete Nail traverse point SSE 10.20 and Concrete Nail West 6.0 and dipped further but could not be sure there was anything further

Page 68: May 24, 1979 Dug into the backhoe at the location of the irons found 5-17-79. Found a 1 3/4" O.D. pipe in the old road appx 3' deep. There was a wood stake in the top of the pipe. We drove a 3/4" x 38" iron in the pipe. LRP } C.N W5.98 C.N S 10.22

Page 83: June 7, 1979 Set CIM over pipe found 5-24-1979 Corner 8' North of ℄ Blacktop E-W road and 7' East of ℄ crushed rock road South.

RP's: (Rec vs what) in power pole #34411 SE 54.34 Pinhole W. end Culvert SW 47.88 2" pipe on E side Fence N & 4' N corner pst N 32.96