X 6-12-1979 CIM but in this final? Gave to 666 8/24/96 (1)
#450206

1/4 corner 2-3 Hi Forest 104-15

6-1877 Hunter P 319 no 313 S 3 J Brewer - J Saulsberry found no satisfactory corner., set stake on line. J Rickert and Ho chains from SE cor 3. Making 39.66 north to NE 3.

6-1877 Hunter P 320 no 314 S 2. Sam Saulsberry, Julius Priebe. found & used corner P 319.
-16 east set stake M & L. 20.01½. to stake set as center S89°E
-16 south " " " 20.00
- meas north. 39.66. to stone set P 319.

6-1895 ~~W Frazer Hunter~~ P 637 no 574 S 2. Carl Battcher, Julius Priebe. Could not find stake P 319. found 1/16 east & center P 320 Re run line and set long. boulder stone as corner replacement
mgl

to further test corner. run line from W 1/4 3 over center 3. this line fell on stone set.

-16 east found Hunterstake P320 set iron pump handle as corner replacement M & L. 19.98 1/2.

-16 south set stake & boulder M & L. 19.99.

-16 center S W 1/4 2. set iron stake at meas not true enters lines. -19.98 north to 1/16 - 19.96 west to 1/16

1940 Co Hwy Dept found iron pump handle P637. 1/2" rod over hub. - 1 1/2" pipe N 33.05 at 1/16 or east.

-16 east 3/4" steel reinf bar. - 1 1/2 pipe S 33.0 1 1/2" pipe N 33.05

1-69 County doesn't seem to have any records - RW still 33'

B109 P76 says all above data on 1/16 corner. reset 1/4 2-3 by reproducing meas & line from Center 2 over pump handle 1319.75 RPs to 1/4 2-3 Hub in paved W N W 100.0 Corner a. PI. Δ 0° 40' Lt Hub in fence line N 66.84 going east

#450206 #2

HI FOREST ¼ CORNER 2-3
Gov't Notes Ball 1853
North on true line between sections 2 & 3.
40.00 set ¼ section post in mound of earth and sod with trench and drove charred stakein centerof mound planted osage orange seed in S.E. corner.

1979 Remon. BK, Pages 59, 78, 79, 89, 90

Page 59 5-17-1979 Ripped at ¼ Cr 2-3 and found a ½" rod 1' deep, 1½' South of ℄ E-W road and in ℄ road South. Raised rod to surface.

Page 78 6-1-1979 Doubled line and measure from the stone found at the Center 2 over the pump handle found at the 1/16th West. The point came .3 West and .19 N of the C.H.D. rod. Removed the rod and dug for 2' West, 1½' North, 1½' South, and 3½' East by 8" deep to clay. We found only a C.H.D. 2x2 hub beneath the rod. The area had been dug on the NW side of the rod. There was still a little

black dirt over the clay but we could find no mark from W. Frasier stone LRP to CHD rod } CN W4.69 CN N4.41

Page 89 6-12-1979 We dug here again after finding S 2-3 which indicated this corner could be further South than we dug before. This time we found an 11" x 7" topped boulder over 2½' long with a stake on its NW side 4½' deep. We set a 1" pipe with an elbow on the East side of the stone and a ½" pipe on the NW side of the stone where the stake had stood (took picture) The corner is .75 E and 2.5 South of the iron used as a traverse point. We set a CIM at the road surface over the stones. The corner is 4' South of E-W road, in line with the fence North, and in ℄ rd. South.

RP's: CSD NW side pp# 12976 SW 43.03
Punch hole top W. end CMP in road South SW 29.47
Punch hole top E end C.M.P. in road South SE 28.45

#450206 (3)

¼ Corner 2-3 High Forest 104-15

1/16th East

Remon BK, Pages 59, 77

Page 59: 5-17-79 Dipped here. Not good dip 4' South of ℄. Set concrete nail over it

Page 77: 5-31-79 Dug on the South side of t.n. Found Will Fraser's pump handle with 2x2 hub on the E side and ¾" rod over it .23 west and .48 South of the t.n. Put the ¾" rod on the west side of the pumphandle and set a ½" iron at the road surface over the pump handle.

This pumphandle is not on line Center 2 to W¼ 2 as Fraser said it was.