1964 Co Hwy Dept set C/M over Frasers pipe. (1)

#450506

1/4 corner. 5-6 Hi Forest 104-15

6-1875 Hunter P285 No 282 & 6 Patrick Holland & others. B Trees cut & gone. no visual evidence of corner. Clm Aver & Pat Holland the fence west was on line and corner post 1 foot west dug and found remains of old stake set new stake. - bearing of 1/4 line west N 89 1/4 E

2/16 south set marked stake M & L. 20.07 S 50' E

6-1898 W Fraser P633 No 572 S 5 L. Eichstaat, T Ragen found old post remains and with an old stake on north side in center of road. - drove long piece of gas pipe in old stake remains - this corner 17 links west of direct line

over)

between section corners N & S. 17 links = 11.22'

46 south set stake M & L 20.07 (1324.62 x 2 = 2649.24)

Meas. N. 40.70 (Gov't 40.28

5-1940 Co Hwy Dept found pipe in road. - ½" re-rod reset
S 5-6 sta 0+00.0 — Sta 46-6 2654.3 corner is P.I. Meas E 2649.31
1964 B 283 " — " " R 2649.24 set C/M. over pipe.

Sp in tele pole. NW 38.15' (1940)

" " power pole

~~Disc in tele pole~~ Disc TP NE 51.53 SSE 105.45

~~Disc in fence post~~

Cross in N end of each headwall conc culv. LE 33.8

~~Set~~ about 3' west of west shoulder of hwy road - C/M. a PI 89° 21½' R+
1964 RPs Sp D TP SSE 105.45 - Sp D TP NW 51.93
Hub W 43.45 - Hub NNW 97.05 - Hub NE 91.2

~~Not found~~.

#450506 (2)

¼ Corner 5-6 High Forest 104-15

11/2/78 Dug on the East side of the C.H.D. CIM. to verify it being over Will Fraser's pipe. Found the CIM over a ½" rod inside a 1"–1¼" pipe 4' deep. Did not dig further.

11/6/78 1/16th South: Dug from a point @ W. Fraser's measure from ¼ Cor 5-6 and on line to the C.H.D. C.I.M. @ S. 5-6, West 2', East 2½', South 3½', and North 3½'. Found nothing.

3-13-85, ¼ Cor 5-6: Found CIM broken to piece. ½" rod below seems OK but does not fit transit tie exactly taken 5-3-79; so set CIC/p 2 .04 WE'ly and .04 NW'ly to fit coord. on Drwg 4-32. Set survey sign on W side. Corner on W¼ side of rd between shoulder & ditch.

5-3-1979

Took transit tie to corner before road construction
Drove a RR spike in C.R. 3 (blacktop) 11' East of ℄
and 38.7 West of pp # 12644 South of 1/4 Cn. 5-6.
We took references to spike 0+00 (drawing 4-32)
RP's Punch mark NW'ly end 26" concrete culvert
WSW 69.09
Punch mark NW'ly end 26" concrete culvert
WSW 69.09
Punch mark SE'ly end 26" concrete culvert
SW 61.29
Then occupied 0+00 and turned an angle
right from the RR spike to the CTM @
1/4 Cn 5-6 of 114° 18' 41" for 337.41 (Had
337.34 in Nov, 1978)

#450506 (3)

HI FOREST ¼ CORNER 5-6
Gov't Notes Ball 1853
North on true line between sections 5 & 6.
40.00 Set ¼ section post.
Bur Oak 10in. S-72 E-230 lks.
Bur Oak 14in. S-55 W-295 lks.