1

9-5-75 Set C.I.M.

#510204

1/4 corner 2-11 Elmira 10 5+ 11.

11-1891 Thos Fraser P462 no 446 L2 Julius Kemp.
Corner gone for years set temp stake Midway 40.03 3/4.

4-1892 Thos Fraser P477 no 456 L 10-11 Waby-Ferries John.
Corner gone set temp point Midway no meas recorded.

1/16 west - set stone 4x8x25 glass underneath M & L.

1/16 center NW 1/4 11. set stone 4x10x24. glass unneath at intersa
of 1/16 lines of NW 1/4 sec 11.

1/16 south - set temp stake. M & L. 19.87 15/16
Came in open pasture left nothing.

9-5-75 Dug area of corner but found nothing. Set C.I.M. obl ½" sq. x 12" spike at intersection of line from N¼ Cor 2 over pipe set in old corner posts at Center 2 and N line of Section 11 (using computed location of NE Cor 11; ie, used T.F.'s full measure N. from ¼ Cor 11-12). Corner lies 16' N of fence E and 13' E of fence S.

CSD in N side gate post ESE 61.84

CSD in NW side oak corner post SW 20.8

60d and disc on NW side 24" Br. Oak SW 41.9

GOV. NOTES - 1853 - WM A JONES

SET ¼ SEC POST MIDWAY 40.15

7" BURR OAK S 68° W 8 LKS (5.28')

6" " " N 88½° W 27 LKS (17.82')

DRY RAVINE About 2 chs WEST

"510204"C 9-29-98 MW EA 71

1/4 Cor 2-11 10S-11 Elmira

Fd CIM set in 1975 in good Condition in pasture. Top down 3" below surface 16' North of old fence Row East and 13' East of old fence South