X 9-5-75 Set stone found in fill back over spot #510206 (1)
11-6-1979 Set ct/cap

1/4 corner. 2-3 Elmira 10 5 -11.

11-1891 Thos Fraser P 462 no 446 & 2 Julius K emp.
Corner in road grade washout area. set stone on
sec line Meas 79.22½ record 79.61 short 38½ lks.
40.00 chs ÷ 39.61 as 39.80 3/4 ÷ 39.41 3/4
South North.

4-1892 Thos Fraser P 483 no 460 & 3 John Ricter.
found corner P 462.
Meas south 39.80 3/4 north 3941 3/4.

9-3-75 Dug away W. half of N-S road with backhoe. Found 2" x 4½" x 24" stone lying flat in fill. Found old road down 3' & worn into clay. Could find no mark.

9-5-75 Dug 6' W (in W. ditch) after measurement.
Found 2" x 4½" mark in clear clay 3½' deep.
Set stone back on mark.

R.P.'s: CSD N side corner post W 14.75
CSD W side telephone pole NE 87.95
corner 5.47 W and .7 N of trav. nail

GOV. NOTES -1853 - [illegible]
SET ¼ SEC. POST AT 40.00 FROM SOUTH - 2640.0
BURR OAK-5" N65½° E 325 LKS - (204.5')

11-6-1979 We set a CIC/1² driven over a ½" pipe on the North side of the stone found and placed over the mark also found 9-5-1975 and at prorated Govt measure and on line from Sec. Cr. 2-3-10-11 to the calc. loc. of N 2-3 (calc. N. 2-3 on line from N 3-4 to N ¼ 2 and at prorated Govt measure as per T. Frost Survey) (continued

#510206 (2)

¼ Corner 2-3 Elmira 105-11

11-6-79 continued:

This corner 1' North of the line of the fence West and 12' West of the center of the N-S road.
RP's: CSD W. side pp SW 57.98
CSD N side corner post WSW 14.79
CSD W side pp NW 133.91

"510206" D

7-27-98
LTA JJ BB

✓ 1/4 COR 2-3 ELMIRA 105-11

FOUND CIC/P² IN GOOD CONDITION DOWN 1.5'

NOW UNDER FIELD DRIVE WEST

11 1/2' W ℄ N-S TWP ROAD

2' S ℄ FIELD DRIVE W

CSO IN PP # 17081 SW 30.91

CSO IN PP # NW 133.91 (1979 133.91)