#510304

1/4 corner 3-10 Elmira 105-11

4-1892 Thos Fraser P477 no 456 L10-11 Wabag Farrier.

old stone found as corner proved 29 1/2 lks too far south and 5 3/4 lks E-W on carefully run line. 2627.6

adjusted corner to place Midway and on line 39.81 1/4.

1/16 east set 2 stones 4x8x25 with glass below M & L 19.90 5/8

1313.8.

4-1892 Thos Fraser P483 no 460 L3 John Rickter.

found corner P477 and 1/16 stone east.

Meas 39.81 1/4 east and west.

2627.6

Gov't Notes Aug 1853

Set quarter sec. post 39.98

10" Blk. Oak S 27° W 55 lks (36.3')

5" Burr Oak N 49° W 13 lks. (8.6')

6-18-76 Visited corner area. Could not determine location without traverse.

MW

6-18-76 (1/16th E) Found 2 stone 18" long 1/2' NE of the corner post to fence E-W-S.

Set 1/2" x 24" iron between stone at corner.

78

"510304" C

11-17-98
MW EA

✓1/4 Cor 3-10 105-11 Elmira

The Corner area is on Top of a Dam I 30' higher than the ditch running Easterly. Set CIC ⌀2 as Corner Midway and on line between Section Corners. The Corner Falls 5' East of N-S Fence and 14' North of Fence East set post and Survey Marker Sign 1' east of Corner