6-22-76 Set 10" C.I.M. over large boulder found (1)

#516404

1/4 Corner 4-9 Elmira 105-11

4-1875 Hunter P340 no 334 S 9 John McGuire found old stake remains in center road. lines with fence south averred by Mr J Coulson as set in line stake which stood in mound until previous year. No mear. set stone in place of stake 22 X 14 X 10 = 4-1878 T.H.

4-1900 Robt Fraser P683 no 607 S 9. J. Rickenbacher found stone slightly S. north center road in line with fences running north & south. No mear or 1/16.

Gov't Notes 8-1853

set Quarter post	40.08			
9" BIK Oak	S.	42½° W	112 lks	(73.92)
6" BIK Oak	N.	37½° W	104 lks.	(68.64)

6-1857 E. P. Bircher
by T. Hunter deputy

Road #24
Meas. from 1/4 Sec post West to
Sec. cor. 4-5-8-9 40.00 chs.

6-17-76 Dug with backhoe & found recorded boulder leaning to the S.W. Dug down & took center of black mark in clay. The stone was 2' deep, in line of fences N. & 1½' South of ℄ of E.-W road.

6-22-76 Set a 10' C.I.M. over the stone.

10-1983

R.P's			
Brace post	N.N.W.	42.58	42.49
Corner post	South	27.98	No good post leaning SO 28.75
4" pine (3rd in row)	S.W.	50.2'	

10-1983 CIM leaning North - Must be straightened to tie from North @ X at SE 4

42.48
50.48

1.63 W
1.48 N

1½ E
1'2 FEN

1½ W

50

#510404 (2)

1/4 Cor 4-9, Elmira, 105-11

10-28-83, 1/4 Cor 4-9: Found 10" CIM leaning badly. Removed and replaced with 16" CIM. Chipped off top of stone beneath to make room for CIM. Corner 1/2' E. of fence North and 2 1/2' West of fence South, and 1' South of E-W road.

RPs: C.S. Disc in West side of brace post NNW 42.48 Spike and CSD (new - apparently didn't put spike in in 1976) in NW side pine tree (3rd West) SW 50.48 The CSD in the corner post to the South in 1976 is not usable since the post is near falling over.