X 7-2-76 Set ½" rod #510804 #1

12-27-82 Set 1"x5" square w/cap 2.18 W. Corc. ℄

¼ corner 8 - 17 Elmira 10 5 - 11.

5-1875 Hunter P 279 no 276. ℄ 8 Julius Kuckenbacker.
found remains 2 old stakes from bearing ℄ N W B T.
left as found. Meas east 39.75

6-1897 W Fraser. P 656 no 585 ℄ 17-20 Town Board.
found N W B T standing - 8" burnoak. N 46° W - 50 lks.
found old stake set stone 3 x 20 x 34 in place stake.

5-21-1900 Robt Fraser P 681 no 606 ℄ 8 Julius Kuckenbacker
found stone set by Fraser, tested by N W B T.
Meas. East 39.75½

① set stake 6.74 lks north 444.84
② set stake 29.675 lks east
③ set stake 6.74 north 2 or 10.265 west from on E sec line.
10" elm S 20° E 43½ lks – 15" W oak N 2° W 148½ lks

1964 Co Hwy Dept B295. Lp in PP NW 46.33
" tele PP NE 4322.
tele P SE 35.57.
assumed corner. Meas south to Assum "4 17-20 5269.66

1935 Co H D B75 P5. found boulder (?) W.F probably set limestone
Sta 52+58.9 – Meas north 2620.3.
Lp Tele pole #172 NE 33.0 – Lp cor FPSE 34.1.
Lp P P #1079 SW 65.7 – Lp P P #1078 NW 32.4

B. 83-P18 stone mon. 1938 RPS.
D in PP NW. 36.1 – D in PP SW 70.0 – Hub NE 63.7
Lp in TP #172 NE 32.6 – Meas north to center 8 2619.9
PI 208+60.8 Δ = RT 0°45' from South

#510804 # 2

1/4 cor 8-17 Elmira 105-11

Gov't Notes

Set 1/4 sec post 39.92 (2634.72)

8" Burr Oak N 46° W. 50 lks. (33')

10" Burr Oak S 10° W 49 lks. (32.34)

6- 1857 E.P. Bircher

by T. Hunter deputy · Road # 24

Meas from 1/4 cor. 8-17 South to Center 17

39.50

6-14-76 Dug  by 5' deep in intersection at CHD rod (remand) Area had been dug but not to clay. Green muck on clay. Found nothing.

6-25-76 Dug again on W. side of previous digging. Found C.H.D. boulder (1935) and 7 frasers stone lying flat

on N side. Could not find mark where stone stood. Slag 4'x8". Boulder 2'W and 1'N C.H.D. rod

7-2-76 Set ½" x 25" rod as corner on line from S¼ 17 (found) and at property W.F. marked over Center 17 (found). Corner came 2.0 W and .72 S of transit point (in ℄) and in ℄ of road E & W.

R.P.'s: NW edge of telephone box SW 71.9
CHD Disc in pp # 2112 NW 45.48 gone 1982
CSD in P.P. (E. side) NNW 120.97
CHD Disc in pp # 2113 NE 45.07 gone 1982
CSD E side pp SSW 181.13 (sloped)
CSD (N. side) Wood fence post in fence on S. side of road E SE 64.10 gone 1982

12-76 Set nail from R.P.s. Dip needle says rod knocked over.

1/4 Corner 8-17 Elmira 105-11 #510804 #3

8-8-77 Tied corner (mail) for road grading.
RP ½" x 7" rod in ℄ road W (W 95.00) and on line to ½" x 7" rod in ℄ road West ℄ W 195.30.

5-14-82, 1/4 Cr 8-17: Found ½" rods set 95.00 West and 195.30 West of corner 8-8-1977. The first iron appeared to be leaning slightly East. The CHD Disc in pp # 2112 NW 45.48, the CHD Disc in pp # 2113 NE 45.07, and the C.S.D. in fence post SE 64.10 all taken 7-2-76 are gone. Other ties taken 7-2-76 not suitable to reset corner accurately.

5-25-82, 1/4 Cor 8-17, Set a spike on line from ½" rod set 195.30 West over the ½" rod set 95.00 West on 8-8-1977. The road here has a huge frost boil so we set nothing further.

We found a 5/8" iron .8 North and 1.4 East (probably CHO)

5-27-82, 1/4 Cor 8-17: Traversed from 1/4 Cor 20-29 to the N 1/4 Cor 5 to check each corner reset from 1976 and 1977 ties. Found point reset at 1/4 Cor 8-17 on 5-25-82 to be out of position and apparently an error was made in taking the 1976 ties or in resetting nail to take 1977 RP's: We moved our point .54 West and took RP's. May move the point .2 South after paving to split private between 1/4 Cor 20-29 and 1/4 Cor 5-8.

→ This point set on the line from the S 1/4 Cor 17 over the Center 17 I set from rods set on RP's in 1977

RP's:- CSD in NW side power pole # 47577 NE 54.88
- Punch hole top N. end CMP NW 43.50
- Punch hole top S. end CMP SW 43.26
- Punch hole top S. end CMP SE 46.27
- Punch hole top N. end CMP NE 44.78

#510804 #4

1/4 Corner 8-17, Elmira, 105-11

12-27-82, 1/4 Cr 8-17: Set a 1" square by 5" long pipe with cap 2.18 West of Concrete E. Corner found 0.93' South and 1.90 West of the C.H.D. P.I. Set Corner ~~taken~~ from tie taken 5-27-82. Took no new R.P's.