#510809

X

1/4 corner. Center 8 Elmira 10 5-11.

5-1875 Hunter P279 no 276. S 8 Salmo Kuckenbacker. set boulder in roadbed. 9x10x17 at true intersection lines. N 1½° W – S 88° 42' W no mean.

10-1897 H Fraser P610 no 555 S 7&8 C Krause. found boulder. P279. removed and placed 3x5x18 limestone slab, then placed boulder on top in identical place as before removal.

1/16 west – set stone 3x10x24 M & L 20.01 3/8 (1320.9 3/19.5 19.99 1/4 M & L)

1/16 north – set short wood stake with iron stake by side

1935 Co Hwy Dept Book 75. P4.
found boulder in roadbed.
sp. fence post ℄ E 57.9 ℄p. tele pole N.E. 96.2
" " " ℄ W 36.6 " power " N W 81.3.
℄ta 26+38.6 a PI Δ 0°2' Rt. 8'48. ℄ta 52+58.9

5-22-1900 Robt Fraser P68 no 60 ℄8
found boulder stone. on east side ℄ middle road
bears south chord. 28 links (18.48' actual 1935 (18.7' bears

1935 B83 P.18 Co. H. D. relied on
℄p in oak W 79.1 ✓ - ℄p in TP SE 82.2
℄p in pp ✓ NW 78.9 ✓
Mean N 2637.0 south 2619.9.

6-23-76 Corner corner on top of hill in 4' cut. Dug with backhoe to check condition. Found road cut into clay.