1. 9-8-75 Set C.I.M. #511104

1/4 corner. 11- 14. Elmira 10 5 - 11.
4-1892. Shoe Fraser P477 no 456 & 10-11 Wiley-Ferrier
Corner complibly gone, set temp point Midway 39.80 1/8.

Gov't notes: set gr. post & stone 18"x12"x2" - pits

9-8-75 Set C.I.M. over 1/2"x6" pipe M&L. Corner comes
3.8' E of corner post to fence North and
under fence East.

"511104" B 9-18-98

✓1/4 Cor 11-14 105-11 Elmira

Fd CIM in good Condition down 15" the Corner is 1' North of Fence East. and 3 1/2' East of Fence line North

"511104" C 9-29-98 MW EA

✓1/4 Cor 11-14 105-11 Elmira
Set post and survey marker
sign 1' North of CIM.