8-29-75 Set C.J.M. #511106 #1

1/4 10 - 11 Elmira 10 5 - 11.

4-1892 Thos Fraser P477 No 456 & 10-11 Raby - Farrier

corner gone for years, plowed out, set stone 3 x 8/12 x 20.

M & L. 39.76 2624.16

1/16 east set limp point M & L 19.93 3/8. 1315.55

1/16 north. set stone, glass below. M & L 19.88.

1/16 west. set stone 3 x 6 x 20, glass below M & L 19.95 13/16.

1/16 south. set stone about 20 x 10, glass below M & L 19.88

1/16 center SE 1/4 sec 10 wedge shaped stone 7 x 8 x 25 glass below - at intersections. no mark.

1936 Co H D B 83 P 10 found 1/16 corner, center SE 1/4 10
stone mon. 28± NE of Center road.

8-11-75 1/16 W Dug around base of corner post and 3' ft to cover T.F's full measure but found only 3" x 8" x 16" limestone lying flat on N. side of corner post (no glass or mark)

8-13-75 1/16 N Dug in old fence line and found 3" x 10" x 24" vertical limestone 1½' deep. Set flat iron on N. side and ¾" rod on S. side

R.P.'s - Spike & C.S.D N. side of blazed 16" Ash SE 47.3'
- Spike & C.S.D. S. side of blazed 18" Oak NE 81.0

1/4 Cor 10-11 Elmira #511106 105-11

8-14-75 1/16 S Found 2 stones 2x10x20 22" deep 1' N of E-W fence. Set 2 irons beside stones (1/2" x 18" and 3/4" x 18") and stood piece of old fence post up on west side of stone
No Tie

8-14-75 Doubled line and measure from Center 10 over corner post at 1/16 E and dug 6'x6' to clay but found nothing. Corner lies in open field

8-29-75 ~~Reg~~ Set C.I.M. (down 14") over 3/4" x 23" rod in open field at 2/3 the distance and on line from Sec Cor. 2-3-10-11 to 1/16 S. of 1/4 Cor 10-11.

Cont Notes

Set 1/4 sec post 40 chs.

6" Burr Oak 5 70½° E 122 lks (80.5')

5" Burr Oak 5 76½° W. 95 lks (62.7')

"S1106" E 11-17-98 mw EM

✓ 1/4 Cor 10-11 105-11 Elmira
Found CIM set in 1975 Now
3.2' deep to Top of Mon in Terrace
built on Contour. Set CTC/P2
over CIM over 3/4" Iron rod
the Corner Falls ± 150' West
of East end of terrace
Set Post f Sign 1' South
of Monument