/

#511709 #1

1/4 Corner Center 17 Elmira 10 5-11

6-1899 Jr Fraser P 656 no 585 & 17-20 Town Board drove stake 40 chains south of N 1/4 17 on N-S 1/4 line. set stakes 50 lks E & W of stake for road grading.

6-1902 Jr Fraser P 40 B & 17 J Jackson & J Gardner. found stake set P 656. reset stake on already establish N-S 1/4 line - reset stake at true mile

Shows	39.94 south of N 1/4 17.	2636.04
	39.91 south to S 1/4 17.	2634.06.
1/16 west set stake	M & L 19.81.	1307.46

Co H Dept 1913. B7 P19
No dec of corner – RPs real close – assumed corner in first Pl

6-1857 E. P. Bircher
by T. Hunter deputy

Road #24
Meas from 1/4 cor. 8-17 to Cor. 17
39.50 and meas west to
1/4 cor 17-18 — 39.14 chs.

6-25-76 Dug with backhoe and found old stake in clay
3½' deep. Put spike in stake and junk around.
Corner 4' N of fence E and 1.7 N of fence W; also
17.66 N and .4' W of traverse nail in ℄.

6-29-76 Set ½" x 24" rod at road surface
R.P.'s CSD S. side of fence post WSW 33.65
CSD S. side of corner post ESE 37.97
CSD E side power pole SW 143.4
CSD E side power pole NW 193.87

¼ Corner Center 17 Elmira 105-11

8-8-77 Tied corner for road grading. #511709
R.P. Set ½" x 2' rod (E 109.44 on E side of 1x2 hub 2½' N of fence E) ~~out~~ on line to ½" x 2' rod set on N side of 1x2 hub 1½' N of fence E + E 225.19 (from Center)

5-14-82, Center 17: All ties taken 6-29-1976 are now gone. CSD in C.P. East is still in port but port has been moved out further. Found ½' iron set to the East in 1977 OK, although the hub set by the first one was gone.