6-16-76 Set CIM #512005

section corner. 19-20-29-30 Elmira 105-11.
11-1894 H Fraser P559 No 514 S30 E Lambert.
J. McCully.
found stone planted as corner, tested
by NW BT still standing 8" bur oak - N68°W 8 links
No mear or 1/16 cor on courses.

6-1899 H Fraser P656 No 585 S17-20 Town board.
found stone P559 tested NW BT standing
mear east 39.90 to 1/4 stone set M & L N89°50'W

1935 B81P37 Co H D mear line south 5270.
did not mention disc of corner.

over

Gov't Notes Sept. 1853

N. 80.00 ch. Set post Corner To Sect. 19-20-29-30

B.T.s Bur Oak 8" N 68° W 8 lks.
Red oak 4" S 89½° E 172 lks
Bur oak 7" S 1° W 565 lks.

6-16-76 Found 2" x 15" x 20" stone 1' S. of 2" pipe corner post to fences E-W-N. Set CIM in place of stone with ½" x 18" rod below and set stone on the S. side of CIM. Corner in line of fences E-W-N

R.P.'s: Spike and CSD S. side blazed 15" ? W 99.4