7-13-76 CIM

1

(1)

#S12104

¼ corner 21-28 Elmira 105-11

4-20-1878 Hunter P337 no 331 S28 N^m Laird.
Corner locall in road washout, one remaining BT 1266 likho
ho settles ener cave corner so set stone 3x15x25
M & L 40.21
1/16 east set stake 20.10½ M & L.
1/16 south set stake 20.00 M & L.
set 1/16 cor center NE ¼ 28 N¼W no mens other.

4-25-1878 Hunter P338 no 332 S21 John Gardner
found corner P337 line north N 3¼' W
set stake on line 15.50 chs south of center 21 per decl.

Foot Notes

Set quarter cor. post M-L 40.06

4" Burr Oak S 88° W. 1266 lks. (835.6)

4" Burr Oak N 41° E. 21 lks. (13.9)

7-7-76 Dug with backhoe 4' deep to bedrock on line from Sec. Cor. 20-21-28-29 to line of E-W fence at Sec. Cor 21-22-27-28 and from line of fence N. East 8'+ (but possibly short of T.H. full measure from SW 21). Found nothing. Condition poor. Much clay fill with stone.

7-13-76 Set CIM over ½" x 2' rod M+L at 2649.01 as per T. Hunter Survey

R.P.'s "T" cut in the NE corner concrete sq. culvert N 45.32

Spike and Disc in 11" Blazed Elm S.W. 61.66

Corner falls in line of fence (far) North, 1' E of ℄ of Rd. S. and 32' South of ℄ of E-W road.

1/4 CORNER 21-28 ELMIRA 105-11 (2)

7-11-94 FD CIM DOWN 18" DEEP IN FILL OF TWP RD
GRADING TO SOUTH. TOOK NEW REFERENCES #512104
R.P.'S PUNCH HOLE IN SW END 24" CMP WNW 60.60
PUNCH MARK IN NE END 24" CMP NNW 63.49
#512104