/ 6-16-76 Set CIM #512105 (1)

section corner 20-21-28-29 Elmira 105-11.
4-1878 Hunter P337 no 331. S28 W^m Laird.
found stake remains in road.- NE & SE BTs standing
BTS - 7" Beak N60°E 7lks - 8" Beak S82°E 90 lks.
tested OK set new stake as corner - stone by side of stake
1/16 south set stake 20.00 M & L. S 3/4 °E.
Meas east 40.21 to M & L. stone

4-1878 Hunter P 338 no 332 S 21 John Gardner.
found corner P 337. no meas, no 1/16, no courses.

6-1899 W Fraser. P656 no 585 S 17-20 town board.

(over)

found large stone set by side of corner fence post. with old stake by side. tested stump of E B tree. (note either error in corner locall or road changed since P 337. would stand checking).
Meas west 39.90 to 1/4 corner stone set M & L.

Gov't Notes

Set Sec. cor. post		80 chs.	
8" Burr Oak.		S 8½° E	90 lks.
7" Burr Oak		N 60° E	71 lks
4" Burr Oak		N 50½° W	127 lks.
4" Burr Oak		S 54° W.	152 lks.

6-16-16 Found 2" x 15" x 24" limestone 3' SW of corner post to fences E-W-N. Set CIM over ½" x 18" rod in place of stone and set stone on the W. side of the CIM. Corner 2' S. of the E-W fence and 2' W of the fence N.

RP's Spike + CSD in corner post NE 3.14 N. 96.13
Spike + CSD W side 12" Burr Oak in fence line N

SECTION 20-21-28-29 ELMIRA 105-11 (2)

#512105

5-21-96 - FOUND CIM IN GOOD CONDITION. SW OF C.P. SAME AS 1976 TIE.