#512106

1/4 corner 20-21 Elmira 105-11.
4-1878 Hunter P 338 No 332 S 21 John Gardner.
Corner missing and BT's gone. but Mr Gardner.
owns that corner 4 way fences exactly where orig
corner lay. used corner post as corner.

Gov't Notes
Set 1/4 sec. post 40 lks.
5" Burr Oak S 75½° W 95 lks
4" Burr Oak S 56½° E 65 lks.

6-1899 W.C. Fraser — Field Book 9 P. 41-42
drawing of Plat shows apparent B.T. — N14½°E 12" Cottonwood
(does not says what was used) 49 links