/ 7-12-76 Set rod #512206 (1)
7-26-85 1" sq piece with cap

1/4 Corner 21 - 22 Elmira 105-11

6-1873 Hunter P 230 no 233 & 22-23 Isaac Fry
John O Fahey
Jennings stat.
Page 139 & 140
~~Corner gone. set stake Mkt. no mark~~ = info. wrong.
T. Hunter Bk 3 p. Survey No. 155 — By digging in center of road
fd remains of old stake, set stone 4½" x 5" x 16"

4-1878 Hunter P 338 no 332 & 21 John Gardner.
found above P 230 in place. ~~no mark~~.

Gov't Notes: set qr. post and stone 8" x 8" x 1" mound 4 pits

T. Hunter Bk 5 p. 57 4-1878 Sec. 21 Gardner
found stone set by me where old ¼ post stood in previous survey
Meas. West 20.21 — 20.21 set 1/16 stake.

7-12-76 Corner corner in bridge. Set ½" x 9" rod as corner on line from stone found at the 1/16 E of Center 22 over the corner post at the Center and at prorated T.H. measure (prorated against Meander ½ mile from N¼ 21 to NE 21.) from the N-S ¼ line of Section 21. Line from fence corner at W¼ 21 over average of E-W fence near Center 21 came to the point above.

R.P.'s: CSD in S. side of 6th post E in fence line E on N side of ditch NE 104.55

CSD in pp #2304 SSE 117.10

CSD in N. side of 3rd wood post in fence line W. 94' N NNW 103.10

#512206 (2)

1/4 Cor 21-22 Elmira 105-11

7-26-85, 1/4 Cor 21-22: Set a 1" sq. pipe 1cap from two remaining RP's (P.P. SE and Fe. post NE (post path shaky)) over two huge new conc. ~~culvert~~ culverts in N-S road. Corner 4½' West of ℄ N-S road, and 4' North of eyeball of fence running East of Center 22 (fe 1000 ± E)

RP's: Punch mark at top West end 1.15 from end)
N'ly conc culvert of pair WNW 22.23
CSD in E side pp # 2304 SSE 117.10