Section Corner 25-26-35-36 Elmira 105-11
#512505
7/23/91 SET C1C/P^2
Govt notes: set post and limerock (20"x10"x2")
Sept. 22, 1853 mound & pits

Corner area on high level area with road at corner area and ravine running easterly and northwesterly with roads following ravines.

THOMAS HUNTER SURVEYED SEC 25 FOR 5-1878 A.S. MORRILL & OTHERS BOOK 5 PAGE 61. CHAINS FROM SW COR TO W 1/4 COR 40.25 chains N 3/4° W

7/16/89 DUG FROM C.P. WEST 5' & FROM 1' SO. OF C.P. TO 4' NORTH TO COVER MEAS. EAST AND NORTH FROM T H 1878 SURVEY. THERE IS A DITCH EDGE WEST 7½' WITH A STUMP OF BURR OAK WEST 7'. THERE IS A LARGE OAK NORTH WITH OLD

OVER ↓

Cont. WIRE IN CENTER THAT WOULD SEEM TO RUN TO OAK STUMP. CONDITIONS POOR 1' TO CLAY WITH MANY ROOTS FD NO STONE OR POST.

7/23/91 County Surveyor Set C/C/pc at fence corner which matches T. Hunter 1878 location and all lines measure E-W-N-S closely agree with this location. The corner lines with fence North East also old fence in brush west ± 200'. the corner is 0.7' west of face of wire post.

TP's

℄ driveway running north, west 23½'

Spike in CSD in 24" Br oak, South 4.41

CSD in So side of corner post, east 0.95'