1/4 Corner 25-26 Elmira 105-11
#S12506

Gen'l notes: set post and deposited Limerock (no size)
Mound & pits

7/23/91 SET CIC / P²

Aerial topo map shows corner area in westerly end of rather steep ravine running east. - farm lane runs west near area doubtful

5-1878 T. Hunter Book 5 p. 61. Sec 25 O.S. Merrill & others
apparently used corner, Meas. South shown as 40.25

8/10/89 DUG WITH BACKHOE, HAD TELE. CO. CUT & SPLICE CABLE ON SO. SIDE OF HOLE AT 8' DEEP, HIT 1" METAL GUIDE STAKE WITH RING ON TOP ALSO BARBED WIRE RUNNING NO. & A PIECE RUNNING EAST, SOUTH OF THIS I PROBED A SOFT SPOT UPON SHOVELING OUT.

Cont →

Cont.
FD HOLE RUNNING TO 11' FEET DEEP. I SCRAPED SOUTH WALL OF HOLE AND FD A POST STUB, THE TOP OF IT BEING 8½' deep THE STUB WOULD HAVE BEEN 3' LONG. I SCRAPED AROUND POST HOLE TO 11' DEEP, FD NOTHING FURTHER. WE ARE DIGGING IN BLACK DIRT WITH LIGHT SEDIMENT DID NOT HIT CLAY PROBED EXTENSIVLY TO 3' AROUND POST HOLE. SET ½" x 3' PIPE W/ UNION AT TOP DOWN IN POST HOLE

7/23/91 County Surveyor Set CIC/ telspar pipe at location of post stub found 8/10/89. Set Pipe because tele. cable would interfere with chain.
Rds & drive way west, north 14½'
CSD in PP# 2795, NW 60.77
& N-S road, east 2'