/ 8-2-85 & CIM #512804 (1)

¼ corner 28-33 Elmira 105-11.

4-1878 Hunter p 337 no 331 & 28 M Laird
T. Hunter Book 5 p 60
corner gone. NW B T standing 10"BO - N 56° W - 144 lks.

Mr Ed Fuchy owns he set fence south in line and 2 rods south which checked with B T.

set stone 3 X 3/9 X 21 at joint

meas west	39.93	2635.4 (1/16 Cor. West apparently set)
meas east	39.87	2631.4 – (Set 1/16 Cor. East = B.T. – S 36° W 8° J.O. 18½ Lks.)

Corner in road on high table land very near to descent into ravine.

See T. Hunter Book 5 p 60 Sec. 33

over.

Govt Notes

Set 1/4 sec. post M+L 40.05 1/2

8" Burr Oak S 57 1/2° W. (67 lks)

10" Burr Oak N 56° W 144 lks.

7-3-85, 1/4 Cor 28-33, & Dug for Hunter's corner as described in Survey No. 1331 in line fence south and 33' from South road fence C.P. - Found stone down 3 1/2' knocked over and broken but base still in place dug well into clay. Pieces together eject Hunter measure. Corner near south edge of road on curve from East to SW. Drove 1" sq pipe at stone location and stood stone on South side

7-8-85, 1/16 East: Dug from a point at Hunter's measure from 1/4 Cor 28-33 (came in Clair fe. N. and ridge So) and on line from 1/4 Cor 28-33 to fe. on North side Rd. @ Sec. Cor. 27-28-33-34 for 3' North, 1 1/2' East, 6'± W, 6'± So to clay. Road cut Line No. old road left.

1/4 Cor 28-33 Elmira 105-11 #512804 (2)

8-2-85, 1/4 Cor 28-33: Set a CIM over a 1/2" x 12" iron at the corner over the stone location. The corner is 1' East of the main line of fence South and ± 4' East of newer fence line North and 8 1/2' South of ℄ E-W road on a curve from SW to E.

R.P.'s:
CSD in pp # 2383 ESE 74.82
CSD in top of 12" corner post NNW 40.57