X 4-9-75 Set CIM. #512805 (1)

section corner 28-29-32-33 Elmira 105-11
4-1878 Hunter P337 no 331 S28 H^m Faird.
found orig stake lying on ground plowed out by Joseph Manahan
intentionally. found remains of lower part below plowing. set
stone 2x5x15 deep with 2x14x22 on top to edge corner.
mens east 39.93 ~~no course or 1/16~~ 1/16 shown in Bk 5 p.60

4-30-1878 Hunter P 341 no 335 S 32 Peter Forestall
found stone P 337.
Mens south. 40.03 no courses or 1/16

Mar 19 32-33 J Kell. B12 P51 S 32 for county (one).

See T. Hunter BK 5 P. 60 & 55 Sec. 33

found stone in place as recorded reset stone on top.
22" elm NNW 95.0
24" Beldr 6' west fence line north 118.0
Meas west 2639.5 to drill set N&L.

22 x 19 x 2 Top
15 x 5 x 2 below.
1938 Meas 52 79.0

P37 1936.

Co Hwy Dept 1963 B 81 + B 104.
flat limestone, east side fence corner.

9-9-75 Found recorded stones and John Kerr's 22" Elm tree NW 95.0 now a 36" Elm. Stone 2' S. of fence line W and in fence line S. Top stone 1½ x 20" x 22". Bottom stone 2 x 5 x 15. Removed stones and set C.I.M. over ¾" x 15" rod as corner. Set 2 x 5 x 15 stone on W side of C.I.M. and 1½ x 20 x 22 on N side up 6". R.P. Spike and C.S.D. SW Side (Kerr) 36 (Now Dead) → Elm NW 95.3

7-30-85
C.I.M. is now 2' East of fence South and 1½' South of fence West.

#2

Section Corner 28-29-32-33 Elmira 105-11

Govt Notes #512805

Set Sec. cor. post 80 chs.

8" Burr Oak	S 78° W	164 lks
7" Burr Oak	N 6½° E (T.H. 61½°)	92 lks.
6" Burr Oak	S 42° E	82 lks.
9" Burr Oak	N 32½° W N 12½° E (T.H.)	225 lks.