#512909 Card #1

1/4 corner Center 29 Elmira 10 5-11

6-1857 Hunter P 33 no 52 & 29.

set corner from orig 1/4 corner entire.

	2633.4	2613.6	
Meas west	39.90 - east	39.60	N 88 3/4° E or N 89 3/4° E
Meas north	39.55 - south	39.30	N 1 3/4° W
	2610.3	2593.8	

Corner in blacktop road. #10 in high level tableland

Note: T. Hunter Book 5 p. 54 Sec. 29 4-19-1878
at "3" set stake near road fence on line between "D" & "H"
also set stakes on Line "D"-"3"

7-2-76 Set drag tooth in ℄ Co. Rd 10 on N-S ¼ line and in line of fences E and W. Drag tooth .6N and 4.32 E of traverse pt.

8-8-77 Tied corner for road grading. Ties to E. edge of rod which calc. show in N-S ¼ line.

RP Punch mark in lug at top S. end CMP in field drive E SE 57.27

Punch mark in lug at top S. end CMP in field drive W SW 46.57

CSO in corner post W 51.23

Ties to Traverse Point Vehrenkamp

Sp & CSO in N side 19" Pine SW 86.38

½" x 2' rod (up 3') on S. side of 1 x 2 hub on So. side of pasture fence NW 91.85

#512909 Card # 2

Center 29 Elmira 105-11

5-14-82, Center 29: Found drag tooth set 7-2-1976 still in blacktop but blacktop surface gone to the North. Checked RP's SW and SE taken 8-8-1977 and found them OK to reset corner after paving.