/

#513004

1/4 Corner 30 - 31 Elmira 10 5-11.

5-1901 W Fraser. P 12 B. S 31 N Powler.

Corner gone. NW B tree standing but too far away to set corner alone. Run line set stake at inters north section line where meas from B T intersected.

Meas west. 39.77 east 40.09 3/4 2624.8 N

new } 10" elm S 65° W 23 1/2 lks. 2646.4 E
new } 8" oak N 85° W 17 lks.

~~N 87 1/4 W~~ N 86 1/2° W ✓ 899 lks } orig. B.T.

gpst

Gov't notes: Set gr. post and stone 24" x 15" x 2" — Trench dug.

Bur oak 10" N 86 1/2° W 899 lks.

over.

This by Sankstone 1969.
spike & hub in boxelder 24" N 1.77.
East-west fence.
spike & hub in 16" elm. N 3.0
spike & hub in 10" elm. in E-W fence NE 41.25.
corner ½" x 30" rod. set on E-W ¼ line? ENE 27.57.
subdivided in proportions of old records - no meas given.

June 1973 Sankstone + Taylor
found 5/8" rod Set above by T. Ferguson for Sankstone 1969
meas. E.T.C. - East - 2645.62
South - 26 31.21

7/13/77 Mn/Dot took R.P's to ½" rod 4' So. of E-W Fe and in Fence South.
CN&D in fence post (So. up 2.0) NW 16.42
CN&D in 30" Oak (So up 2.0) SW 58.56