/ 9-10-75 1" square shaft as corner #1
Found by Fillmore Co. Surv.
#513204

1/4 Corner south 1/4 32 Elmira 10 5 - 11.
4-1878 Hunter P 341 no 335 S 32 Peter Forestall.
found stump N W B tree which placed corner at
corner post & fence running south - accepted post as cor.
1/16 north set stake M & L 20.04.

12-1886 Hunter P 418 no 407 S 32 L Bauer.
found corner P 341. set new stake
1/16 north set stake M & L 20.04.
1/16 east set stake M & L 20.01 N 89° E

(over)

3-1938 J Kerr B12 P51 & 32 for Co Hwy Dept.
found iron bar in pile stones in field.
RP drill rod. AZ 180° 48' 215.4. 2' north of 20" brook tree:
RP with transit on drill rod which lies 2.5' North 20" burroak.
AZ to 1/4 cor. 0°48' 215.4.
AZ to windmill tower no 1- 312°17'
AZ " " " no 2- 327°45'
AZ " " " no 3- 98°55'

Gov't notes: Sept. 1853
Set Qr. Sec. Post

B.T.'s Burr oak 6" N 78° W 62 links
Burr oak 5" N 75° E 19½"

Dave Knutson - Fillmore Co. Surveyor, fd iron bar in early 1975

#513204 #2

1/4 Corner S 1/4 32 Elmira 105-11

9-10-75 Went to corner located by Dave Knutson, Fillmore Co. Surveyor. Corner a 1" square shaft in cultivated field. Corner lies 18.5' N of E-W fence and in line with Tree line S. . Set 3/4" x 20" rod S. 230.0 on line between ~~section~~ 1/4 corners, and 5/8" x 9" rod 2 1/2' N of E-W Fence. SW 234.59