X

#513206

1/4 corner 31-32 Elmira 10 5-11.

12-1886 Hunter P418 no 407 S32. L. Bauer. = Field Book 14 P 28

found stone as corner, tested both B trees with marks plain

1/16 south set stake M & L 19.95½ (~~1317.5~~ 1317.0 N 2° W.

3-1932 J Kerr B12 P51 S32 for Co Hwy Dept.

found stone. ~~2647.5~~ 2636.4 north — 2634 south.

12" ash S E 28.8 — " (sandstone 1964) 8" ash 46.5

5-1901 H Fraser P120 S31 M Powler.

found stone & stake set as corner. test BT stamp No mens (ones)

1936 Co Hwy Dept B 81 P 37 104
2 x 12 x 18 limestone up 6" found. ran line east 5277.2
small limestone either side."

~~1969 Sanborn 1969 found drill steel under boulder~~
~~fence junction about 10' east of fence. south. (could be NE 31)~~
IR NE31 2-1970
Co H D. B 295 1964. found limestone in gully area
meas north 2637.46 - 1599.87 north to center road.

June, 1973 Sandstone & Taylor
Found Limestone (up 3") set ½"x2' pipe on W. side
elec. meas. on Traverse — 2636.24 North To Sec. Cor.
2629.18 South To Sec. Cor.
2641.95 West To Existing Center Sec.

Govt Notes Set 1/4 sec post mkd 40.
6" Burr Oak S 10° E 133 lks
10" Burr Oak S 64½° W. 103 lks