#513209

/

Elmira 10 5-11

Center 32

1/4 corner

4-1878 Hunter P341 no 335 S 32 Peter Forestall.

found stake anered by Forestall & E Halloren as run in by surveyor as true corner. Very brushy running west. Run line east to 1/4 corner but not west to check accuracy of corner.

1/16 south set stake N 8 W 20.04.

12-1886 Hunter P418 no 407 S 32 L Bauer.

found above stake. To be west of N-S 1/4 line.

accepted correct as to E-W 1/4 line.

1/16 south set stake midway old stake & S 1/4 cor & on true N-S 1/4 line 20.04

(over)

set 1/16 stake center of E 1/4 32 M & L 20.03 E-W 1/16 line.
set 1/16 stake center of W 1/4 32 M & L 19.98½ E-W 1/16 line.
set 1/64 stake between above and 1/16 cor on West sec line 9.99¼.