X Set C.I.M Sept '75 #513306 (1)

1/4 corner 32-33 Elmira 105-11.

4-1878 Hunter P341 No 335 S 32 Peter Forestall.

Corner gone, in open field, no knowledge by anyone.

run line N 1/4 L. 40.03 set stone 19x8x4 with stake by side.

1/16 south set stake 20.01 1/2 N 1/4 L.

12-1886 Hunter P418 No 407 S 32 L Bauer.

found 1/16 corner. stake and stones - used for line west.

1936 Co Hwy Dept B 81 P37 ~~P 104~~

limestone by fence corner. used as post brace or support

Meas west 5277.2 to 1/4 31-32.

---

see T. Hunter BK 5 P. 60 over

September, 1975 Found pointed limestone standing up and partially out of ground 3' E of fence N and 4½' N of fence E. Accepted as corner location after digging and set C.I.M over rod. (7-30-85 now C.I.M. is 3' North of Fence East and 4½' No. of Fence west.) New C.P. to Fence N & E

R.P. Spike and CSD N side 12" Box Elder
WSW 69.44

9-15-75 (1/16 S) Went to computed location of corner but could not find recorded corner. Corner falls N of Highway 30 on steep embankment.

Gov't Notes Set 1/4 Sec post M+L 40. chs.
10" Burr Oak N 41° W. 190 lks
12" Burr Oak N 8° E 935 lks.

¼ Cor 32-33 Elmira 105-11
#513306

7-31-85, 1/16 East: Dug from t.n. (set in ℄ road and in line fence West) for ½' West, 6½' East, 3' North, and 5' South by 1½' deep to clay. Found nothing. Road in cut on west side. Not very good condition. Line to post hole found at the 1/16 East of the Center 33 came 2.7 South of t.n. and full meas from ¼ Cor 32-33 came 3.73 East

8-13-85, 1/16 South: Traversed into old fence corner to fence West and South. Dug around and found post hole. Post hole 4.3 North and 10.5 East of calc. 1/16 between present corners.