Section Corner South Sec. 35-36 #513605 Elmira 105-11
Gov't Notes: Sept. 1853 8/9/89 SET CIM OVER 60d SPIKE
Set Post for Corner, built mound with trench, drove charred stake in center, planted Apple tree seeds in N.W. Corner

7/7/89 DUG WITH BACKHOE FD POST STUB JUST BELOW GRASS (POST STUB 24" LONG, 7" DIA.) THE POST STUB IS 2' No. OF MAINLINE OF FENCE EAST AND 60' WEST OF PROP FENCE RUNNING So. THE BOTTOM OF THE POST WAS SETTING ON BEDROCK, NO SIGN OF ANYTHING ELSE NEAR POST. DUG FROM 4' WEST OF POST STUB TO 5' EAST; N, S 4' FROM POST STUB 1.5' DEEP TO CLAY (FD NOTHING FURTHER)
8/9/89 SET CIM @ POST LOCATION FD 7/7/89
COULD NOT DRIVE TELSPAR BECAUSE OF BEDROCK
SET 60d SPIKE BELOW CIM RP's

OVER ↘

Cont.
N-S FENCE ON SMALL PARCEL PROP LINE EAST 60', STUB FENCE NORTH EAST 31' CORNER LINES WITH MAINLINE FENCE EAST, & DRIVEWAY TO AUTO SAOPW 13.0' & NE-SW TWP RD N.W. 156.0'

