#5136066

1/4 CORNER 35-36 ELMIRA 105-11

8/9/89 SET C.I.C. 1/2" @ STAKE MARK

GOV. NOTES - 1853

SET 1/4 SECTION CORNER POST MKD 40 LKS 2640

BUILD MOUND DROVE CHARRED STAKE IN CENTER

AERIAL MAP SHOWS CORNER IN HIGH LEVEL PLATEAU

ROAD COULD BE NORTH OF CORNER STONE

COMMON LAND ON WEST SIDE OF SECTION LINE

7/21/89 DUG WITH BACKHOE TO COVER M'L PT. FROM POST @ SO 35-36 TO FENCE INT. @ SEC COR 25-26-35-36. THIS PT IS ON WEST DITCH SLOPE OF N-S TWP RD. 17' WEST OF ℄. THERE IS A OLD ROAD OUT HERE WHICH WOULD MEAN THE CORNER WOULD HAVE BEEN BENEATH THE ROAD. THERE IS A SILT LINE Cont.

Cont.
ABOUT 2' WIDE & 8" DEEP RUNNING S.E.
ABOUT 3' BELOW OLD ROAD COND. WERE
NOT GOOD. WE FD. A 2" DIAMETER BLACK
HOLE BELOW THIS SILT LINE RUNNING DOWN
6" INTO CLAY THE SILT LINE OF A DITCH
PROBABLY WASHED OUT PART OF THE SPOT.
A GOOD CHANCE THIS IS THE STAKE LOCATION.
8/9/89 SET 4' LONG TELSPAR/C.I.C. @ STAKE
MARK LOCATION ON WEST DITCH SLOPE OF
N-S TWP RD. RP's
C.S.D. IN PP# 2764 NNW 119.17
℄ N-S TWP RD. E. 14'
LEFT LOCAL SPIKES DOWN 3" SE 28.17
NE 29.87