9/1/92 set G.I.C. 1P² at post mark location
#520204

¼ corner 2-11 Arivaca 10.5-12.

5-1877 Hunter P311 no 305 d11 Hopkins
Corner gone- B true disagree in bearings. Man that set
fence south avers he set corner post where ¼ post stood
took corner fence post as corner.

1/16- south set stone 6 x 9/10 x 19 M d L 20.08 N 1° W

1/16 center NE ¼ 11 set stake 19.93½ M d L E-W 1/16 line N 89¾° E

Gov. NOTES - OCT 6, 1853
WEST ON TRUE LINE BETWEEN SECTIONS 2 + 11
VAR 9° 40' E
39.95 SET QR. SECTION POST
BR. OAK 6 S 61½ E 29
W. OAK 13 N 42° W 50
79.90 TO SECTION CORNER

1/4 COR 2-11 10S-12 6/12/88 SET SPIKE 1' SOUTH OF CORNER POST FENCES N-E-W

9/1/92 COUNTY SURVEYOR Dug for corner post used by T.H. in 1877 Found 10" square blk mark bottom at 3' deep with wood, wire staples in it. Set C.I.C. 1P² at post mark location. The corner falls in line of fence North & 3' South of main line E-W fence

2P's CSD in corner post to fence E-W-N North 2.96'

CSD in brace post E.N.E 7.93'

nailed survey marker sign on south side of corner post.